UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells			
1. Type of Well GAS	070 mmilikal	5. (N, M) 6.	Lease Number SF-079367 If Indian, All. or Tribe Name
		7.	Unit Agreement Name
2. Name of Operator MERIDIAN OIL		8.	San Juan 27-5 Unit Well Name & Number
3. Address & Phone No. of Opera PO Box 4289, Farmington, NM		9.	San Juan 27-5 U #160 API Well No. 30-039-20646
4. Location of Well, Footage, S 1800'FNL, 1500'FWL, Sec.31,			Field and Pool So.Blanco Pict.Cliffs County and State
12. CHECK APPROPRIATE BOX TO IN			Rio Arriba Co, NM
X Subsequent Report Final Abandonment	Plugging Back Casing Repair Altering Casing Other -	New Construc Non-Routine Water Shut o Conversion t	Fracturing ff
11-27-95 TIH, tag TOC @ injection. Plu 2 sqz holes @ pump 80 sx Cla surface. WOC.		@ 1788'. Could B" cmt @ 1650-1 wn csg & out br ut bradenhead. l csg w/42 sx C	not establish 850'. TOOH. Perf adenhead. Plug #3: Circ 1 bbl cmt to
• 33			BEG - E (335
			OE, ALL BAY
14. I hereby certify that the			e 11/29/95
(This space for Federal or Stat	e Office use) Title	Date	
CONDITION OF APPROVAL, if any:			

APPROVED

DEC 01 1995 Isl Duane Spencer DISTRICT MANAGER