

NO. OF COPIES RECEIVED	
DISTRIBUTION	3
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.
E 2825-6

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name S.J. 28-7 Unit
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name S.J. 28-7 Unit
3. Address of Operator P. O. Box 289, Farmington, New Mexico 87401	9. Well No. 171
4. Location of Well UNIT LETTER I 1570 FEET FROM THE South LINE AND 1150 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 27N RANGE 7W N.M.P.M.	10. Field and Pool, or Wildcat So. Blanco P.C. & Undesignated CH
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Rio Arriba

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to permanently plug and abandon the Chacra zone in this well by removing the packer presently in the well and spotting a cement plug to cover the Chacra perforations and fill the casing to a point above the Pictured Cliffs formation. Abandonment would be completed by shutting in the well at the master valve until the Pictured Cliffs zone is depleted.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Frank T. Chavez TITLE Production Engineer

DATE 5-30-80

Original Signed by **FRANK T. CHAVEZ**

APPROVED BY SUPERVISOR DISTRICT 3 TITLE SUPERVISOR DISTRICT 3

DATE

JUN 6 1980

CONDITIONS OF APPROVAL, IF ANY: