

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	5. LEASE DESIGNATION AND SERIAL NO. SF 079391
2. NAME OF OPERATOR El Paso Natural Gas Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 4289, Farmington, New Mexico 87499	7. UNIT AGREEMENT NAME San Juan 27-5 Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650'S, 850'E, T-27-N, R-5-W	8. FARM OR LEASE NAME
14. PERMIT NO.	9. WELL NO. #175
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6610' GL FARMINGTON RESOURCE AREA	10. FIELD AND POOL, OR WILDCAT South Blanco P.C.
	11. SEC., T., R., M., OR B.M. AND SURVEY OR AREA I, Sec. 7, T27N, R5W
	12. COUNTY OR PARISH Rio Arriba
	13. STATE NM

RECEIVED
MAY 10 1985

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	PULL OR ALTER CASING
FRACTURE TREAT	MULTIPLE COMPLETE
SHOOT OR ACIDIZE	ABANDON*
REPAIR WELL	CHANGE PLANS
(Other)	

WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*
(Other)	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-7-85: MOL & RU. Unseat donut and packer. T.O.O.H. with 107 jts. 1 1/4" EUE tubing. Remove packer & trip back in hole with tubing. Spot 823', 23 sx class B cement plug to cover perfs, Fruitland, Kirtland and Ojo Alamo. Displace with 9 lbs. gal. gel. Trip out with tubing and SDON.

5-8-85: Rig up wireline and tag, initial cement plug. Run up to 175' and perf. Trip in and establish circulation to surface with 55 sx cement plug. Cut off surface pipe and casing. Install maker, rig down and move off.

RECEIVED
MAY 15 1985
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

Benny A. Wiet

TITLE Production Engineer

DATE May 10, 1985

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

*See Instructions on Reverse Side

NMOCC