FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

UNITED STATES UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)

Form approved. Budget Bureau No. 42-1 5. LEASE DESIGNATION AND SERIAL NO.

ALTERING CASING

ABANDONMENT*

Completion"

DELTAR	Contract No. 92			
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)		6. If INDIAN, ALLOTTEE OR TRADE NAME Jicarilla Apache		
OIL CAS WELL AT OTHER		7. UNIT AGREEMENT NAME		
Z. NAME OF OPERATOR		8. FARM OR LEASE NAME		
Northwest Pipeline	Jicarilla 92			
3. ADDRESS OF OPERATOR		9. WELL NO.		
P.O. Box 90 Fa	rmington, New Mexico 87401	6		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10. FIELD AND FOOL, OR WILDCAT Tapacito Pictured Cliff: 11. SEC., T., R., M., OR BLK. AND SURVEY OR ARKA		
910' FNL				
		Sec. 31, T27	'N, R3W	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE		
	7153' GR	Rio Arriba	N.M.	
16. Check	Appropriate Box To Indicate Nature of Notice, Report, o	r Other Data		
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING W	ELL	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIPE PROPOSED OR COMPLETED OFERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

Tested csg. to 4000 PSI - OK. Ran Gamma Ray Collar Correlation Log 11-14-75 and perforated from 3952' to 3976', 3990' to 3998', and from 4016' to 4024' w/24 shots per zone. Brokedown and pumped 250 gal. 15% HCl. Fractured w/30,000 gal. treated water and 25,000# 10/20 sand. Dropped one set of 24 ball sealers after pumping 12,000# of sand.

Shut well in for gage. 11-18-75

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS



SIGNED	TITLE	Production Engineer	DATE	11-21-75
APPROVED BY	TITLE		DATE	