

submitted in lieu of Form 3160-5

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator  
MERIDIAN OIL

3. Address & Phone No. of Operator  
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M  
1120' FNL, 1065' FWL, Sec. 14, T-27-N, R-3-W, NMPM

5. Lease Number  
Jic Contract 89

6. If Indian, All. or  
Tribe Name  
Jicarilla Contract

7. Unit Agreement Name

8. Well Name & Number  
Jicarilla 89 #2A

9. API Well No.  
30-039-21811

10. Field and Pool  
Gavilan Pictured Cliffs/  
Blanco Mesaverde

11. County and State  
Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input checked="" type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other -
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Conversion to Injection

13. Describe Proposed or Completed Operations

4-27-95 MIRU. ND WH. NU BOP. TOO H w/1876 jts 2 3/8" tbq. RU, ran gauge ring to 5650'. Set 4 1/2" RBP @ 3860'. Roll hole w/KCl wtr. TOO H. RU, ran CET @ 300-3860'. Good cmt in zone of interest. RD. TIH w/FB pkr, set @ 60'. RU. PT on csg failed. RBP leaking.

4-28-95 TIH w/RBP, set @ 3847'. TOO H. RU, dump sd on RBP. Perf Pictured Cliffs @ 3607, 3610, 3634, 3643, 3647, 3657, 3663, 3670, 3680, 3686, 3702, 3739, 3746, 3751, 3756, 3762, 3774, 3779, 3782, 3792, 3797, 3803, 3815 w/2 SFP, 46 holes total. TOO H. Spot 1500 gal acid. RU, frac Pictured Cliffs w/186,580# 20/40 Brady sd, 476 bbl 20# linear gel, 759,000 SCF N2.

4-29-95 CO after frac.

4-30-95 CO after frac. Pkr will not release. TIH w/fishing tools. TOO H w/pkr. TIH, tag fill @ 3778'.

5-1-95 CO @ 3778-3838'. Blow well.

5-2-95 Blow well. Lost flapper valve. Could not latch onto RBP. Fishing.

5-3-95 TOO H w/RBP & fishing tools.

Continued on back

14. I hereby certify that the foregoing is true and correct.

Signed Robert Kent Title Regulatory Affairs Date 5/9/95

(This space for Federal or State Office Use)  
APPROVED BY Robert Kent Title Chief, Lands and Mineral Resources Date JUN 2 1995  
CONDITION OF APPROVAL, if any: