Form 9-331 (May 1963)

TEST WATER SHUT-OFF

FRACTURE THAT

SHOOT OR ACIDIZE

REPAIR WELL

DEPARTMENT OF THE INTERIOR (Other instructions on re-

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

GEOLOGICAL SURVEY

Form approved. Budget Bureau No. 42-R1424

V	NOTICES	AND	DEDODTC	ON	VA/ELLC

5.	LEAS	E DES	IGNATI	ON A	AND	SERIA	L NO.
l	SF	079	107				
		. i. 🚊		-			
6.	IF IN	DIAN.	ALLOT	TEE	OR	TRIBE	NAME

REPAIRING WELL

ARANDON MENT*

SUNDRY	Y NOTICES AND REPORTS ON WELLS	a the		
(Do not use this form Use	for proposals to drill or to deepen or plug back to a different reservoir. "APPLICATION FOR PERMIT—" for such proposals.)			
<u>, , , , , , , , , , , , , , , , , , </u>		7. UNIT AGREEMENT NAME		
WELL GAS WELL	OTHER			
. NAME OF OPERATOR		8. FARM OR LEASE NAME		
Consolidated Oil	& Gase, Inc.	NCRA		
. ADDRESS OF OPERATOR	9. WELL NO.			
1860 Lincoln St.	1-E			
LOCATION OF WELL (Report	10. FIELD AND POOL, OR WILDCAT			
See also space 17 below.) At surface		MesaVerde/-Dakota		
1550' FN	11. SEC., T., R., M., OR BLK. AND SURVEY OR ARBA			
		"B" Sec22, T26N, R7W		
4. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12, COUNTY OR PARISH 13. STATE		
	6928' GR	Rio Arriba NM		
6.	Check Appropriate Box To Indicate Nature of Notice, Report	, or Other Data		
NOTICE	E OF INTENTION TO:	UBSEQUENT REPORT OF:		

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

- 10-7-79 Surface 370' (8-5/8") 13-3/4 hole. Cement 175 sacks no returns 125 sacks down outside- got 25 sacks return.
- 10-22-79 Log: Drill 7-7/8" hole to 7560' w/mud Ran Sch. IES log & Density Neutron.
- 10-23-79 Ran 185 jts 5½" 15½# K-55 csg. to 7541' w/DV tool @ 5605 Cement 1st stage w/100 sks 65/35 poz mix w/12% gel & 165 sks 50/50 poz mix w/4% gel: Cement 2nd stage w/165 sks 65/35 poz mix w/12% gel & 200 sks 50/50 poz mix w/4% gel Plug down 8:15 a.m. 10-23-79

Λ .				· · · · · · · · · · · · · · · · · · ·	
8. I hereby certify that the foregoing is true and correct					
SIGNED Veryl Moore	TITLE _	Production	Superintendent	DATE 10-29-79	
(This space for Federal or State office use)			+		
		· · · · · · · · · · · · · · · · · · ·			
APPROVED BY	TITLE _	<u> </u>	<u></u> ,*	DATE	
CONDITIONS OF APPROVAL, IF ANY:		•	•	N.	