

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

March 10, 1986

Ms. Kay Eckstein Columbus Energy Corp. P.O. Box 2038 Farmington, NM 87499

NCRA #1E G-22-26N-07W Re:

Dear Kay:

Packer leakage retest on the referenced well indicates a packer or tubing leak.

In order to comply with Rule 112-A and the order authorizing the multiple completion, you are hereby directed to take immediate remedial action.

If you have any questions, please contact this office.

Yours truly,

Charles Gholson

Oil & Gas Inspector

CG/dj

xc: Well File