			1	
Form 9-331 (May 1963)	UNITED STATES	SUBMIT IN TRIPLICATE®	Form approved.	404
(314) 1003)	DEPARTMENT OF THE INTER	IOR (Other instructions on re-	Budget Bureau No. 42-R1- 5. LEASE DESIGNATION AND SERIAL N	
	GEOLOGICAL SURVEY		Contract 237	
C	JUNDRY NOTICES AND REPORTS	ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NA	ME
	this form for proposals to drill or to deepen or plug Use "APPLICATION FOR PERMIT-" for such p	proposals,)	Jicarilla Apache	
1. OIL [V] GA			7. UNIT AGREEMENT NAME Ea	~ •
WELL W	ELL OTHER		Puerto Chiquito Ma	ncos
<b></b>	ontin-Greer Drilling Corp.		O. FARM OR LEASE NAME	
3. ADDRESS OF OPE.	<u> </u>		9. WELL NO.	
221 Petroleum Center Building, Farmington, NM 87401			40 (E-19)	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)			10. FIELD AND POOL, OR WILDCAT H.	ast
At surface	r below.)		Puerto Chiquito Ma	ncos
	•		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
1980' FN	L, 660' FWL, Sec. 19, T-27N	, R <b>-1</b> E		
			Sec. 19, T-27N, R	-1E
14. PERMIT NO.	15. ELEVATIONS (Show whether D		12. COUNTY OR PARISH 13. STATE	
	7115	GR	Rio Arriba   New M	exic
16.	Check Appropriate Box To Indicate 1	• • •		
	NOTICE OF INTENTION TO:	SUBSEQI	UENT REPORT OF:	
TEST WATER SH	DUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAS	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDI		SHOOTING OR ACIDIZING	letion x	
REPAIR WELL	CHANGE PLANS	(Note: Report results	of multiple completion on Well	
(Other)	ED OR COMPLETED OPERATIONS (Clearly state all pertine)		letion Report and Log form.)	8 D Y
proposed work	c. If well is directionally drilled, give subsurface local	tions and measured and true vertice	al depths for all markers and zones pe	rti-
	·		•	
Tested ope or gas.	en hole from 42971 to 43461	. Recovered water	r, no show of oil	
or gas.	en hole from 4297' to 4346' ack with cement plug from 4		, no show of oil	
or gas. Plugged ba	ack with cement plug from 4	346; to 4200;.	r, no show of oil	
or gas. Plugged ba		346; to 4200;.	r, no show of oil	
or gas. Plugged ba 8-6-81 H	ack with cement plug from 4 Perforated from 4152' to 41	346' to 4200'. 86'.	, no show of oil	
or gas. Plugged ba 8-6-81 H	ack with cement plug from 4	346' to 4200'. 86'.	r, no show of oil	
or gas. Plugged ba 8-6-81 H 9-1-81 H	ack with cement plug from 4 Perforated from 4152' to 41	346: to 4200:. 86:. 25:.		
or gas. Plugged ba 8- 6-81 H 9- 1-81 H	ack with cement plug from 4 Perforated from 4152' to 41 Perforated from 4075' to 41	346' to 4200'. 86'. 25'. from perforations.		
or gas. Plugged ba 8- 6-81 H 9- 1-81 H	ack with cement plug from 4 Perforated from 4152' to 41 Perforated from 4075' to 41 Pested show of oil and gas	346' to 4200'. 86'. 25'. from perforations.		
or gas. Plugged ba 8- 6-81 H 9- 1-81 H	ack with cement plug from 4 Perforated from 4152' to 41 Perforated from 4075' to 41 Pested show of oil and gas	346' to 4200'. 86'. 25'. from perforations.		
or gas. Plugged ba 8- 6-81 H 9- 1-81 H	ack with cement plug from 4 Perforated from 4152' to 41 Perforated from 4075' to 41 Pested show of oil and gas	346' to 4200'. 86'. 25'. from perforations.		
or gas. Plugged ba 8- 6-81 H 9- 1-81 H	ack with cement plug from 4 Perforated from 4152' to 41 Perforated from 4075' to 41 Pested show of oil and gas	346' to 4200'. 86'. 25'. from perforations.	DEC 7-1991	
or gas. Plugged ba 8- 6-81 H 9- 1-81 H	ack with cement plug from 4 Perforated from 4152' to 41 Perforated from 4075' to 41 Pested show of oil and gas	346' to 4200'. 86'. 25'. from perforations.	DEC 7-1991	
or gas. Plugged ba 8-6-81 H 9-1-81 H	ack with cement plug from 4 Perforated from 4152' to 41 Perforated from 4075' to 41 Pested show of oil and gas	346' to 4200'. 86'. 25'. from perforations.	DEC 7-1991	

8. I bereby certify that the foregoing is true and correct

SIGNED VICE-President DATE Dec. 3, 1981

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

DEC 04 1981