Form 9-331 Form Approved. Dec. 1973 Budget Bureau No. 42-R1424 UNITED STATES 5. LEASE DEPARTMENT OF THE INTERIOR 079492 SF **GEOLOGICAL SURVEY** 6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME SUNDRY NOTICES AND REPORTS ON WELLS San Juan 27-5 Unit (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) 8. FARM OR LEASE NAME San Juan 27-5 Unit well Q well other 9. WELL NO. 2. NAME OF OPERATOR 98E El Paso Natural Gas Company 10. FIELD OR WILDCAT NAME Blanco MV & Bas. Dakot 3. ADDRESS OF OPERATOR -87401 P.O. Box 289, Farmington, NM 11. SEC., T., R., M., OR BLK. AND SURVEY OR Sec. 14, T-27-N, R-5-W 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 AREA / 1840'S, 1120'W below.) NMPM AT SURFACE: 12. COUNTY OR PARISH 13. STATE AT TOP PROD. INTERVAL: New Mexico Rio Arriba AT TOTAL DEPTH: 14. APNNO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6612' GL SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (NOTE: Report results of multip PULL OR ALTER CASING change on Form 9-330 MULTIPLE COMPLETE CHANGE ZONES ABANDON\* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* ---5-13-81: Spudded well. Drilled surface hole. Ran 5 joints of 13 3/4", 48 H-40 surface casing 208' set at 222'. Cemented w/ 325 cf. cement. Circ. to surface. WOC 12 hours; held 600#/30 minutes. Subsurface Safety Valve: Manu. and Type \_ Set @ \_\_\_. 18. I hereby certify that the foregoing is true and correct DATE \_\_\_\_\_May 14,1981 Drilling Clerk (This space for Federal or State office use) ACCEPTED TO A RESURB APPROVED BY DATE CONDITIONS OF APPROVAL, IF ANY: BAY 1 8 1981 Managed No Dignast See Instructions on Reverse Side