17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measurec and true vertical depths for all markers and zones pertinent to this work.)*

8. G. John AL SURver

FARCE BELLEVIEW, N. W.

12-10-81: PBTD 5570'. Pressure tested casing to 3500#, Held Ok. Perfed Mesa Verde: 5160,5194,5198,5202,5206,5210,5226,5230,5234,5244,5272,5286,5296,5305,5330, 5346,5380,5446,5468,5484,5505' W/1 SPZ. Fraced w/ 58,000# 20/40 sd, 116,000 gal. wtr. Flushed w/ 6510 gal. wtr.

Perfed Chacra:

CHANGE ZONES

ABANDON* (other)

> 3775,3779,3784,3788,3851,5856,3860,3872' W/1 SPZ. Fraced w/38,000# 20/40 sd, 76,000 gal. wtr. Flushed w/ 5628 gal. wtr.

Subsurface Safety Valve: Manu. and Type			Set @	Ft.
18. I hereby certify that the foregoing is t	rue and correct	DATE _	Dec. 14, 1981	
	(This space for Federal or State office u	se)		
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE	ACCEPTED FOR RECO	
			DTC 1 g 1981	

NMOCC

FARMINGTON DISTRICT Sam BY

MANAGE AND STREET