				UNIT	ED STA	TES	811	BMIT II	TRIPLIC	ATE		ct Bu	reau N		-0135
Formerly 9		DE	PART			EINTER			tructions o	n / e	. LEASE D			I, 198	
.,			BURE	AU OF L	AND MA	NAGEMEN	1T				NM C	3547	7		
(Do no	SUN t use thi	UDRY	NO	ICES A	AND RI	EPORTS epen or plug	ON W	ELLS different	reservoir.	6	. IF INDIA	AN, ALL	OTTER	OR TRIB	E NAME
		Use	"APPLIC	ATION FO	OR PERMIT	for such	proposals.)	F 1 1	/	<u> </u>	. UNIT AO	REVE	NT MAM		
앨. □	GAS	\mathbf{x}	OTHER			1 \		L_	V <u> </u>	' '				•	
Z. NAME OF O		- AA	OTHER				- HIN	1919	85	- <u>-</u>	. FARM OF	R LEAS	E NAME		
3				Caulk	ins Oil	Company	v		•			e c h '			
3. ADDRESS OF	POPERATO	R.				FARM	U OF LA	ND MA	NAGEMEN RCE ARE	- J	. WELL N				
				P.O.	Box 780	Farming				`	45-N	M			-
4. LOCATION O	F WELL (Report	location	learly an	d in accorde	ance with any	y State req	ulrement	s.*	1	O. FIELD	AND PO	OL, OR	W.IFDCV.	r
At surface		,									lanco				asin
				990'	F/N and	990 ' F/	/W			1	1. SEC., T. SURV	DT OR	., OR BL	E. AND	
14. PERMIT NO				15. Et.	EVATIONS (SI	how whether D	P, RT, GR. et	ic.)		$\frac{S}{1}$	ection 2. COUNTY	1 33	ARIBHI	NOTE	n o W
	•						6577	•		- 1	io Arı		l.		
						1 1						LUG		ICM IN	exico
16.		C	heck A	ppropria	te Box To	Indicate I	Nature o	l Notice	, Report,	or Oth	er Data				
		NOTICE	OF INTE	TION TO:		_	1		au	BEEQUEN:	TROPER 1	OF:			
TEST WAT	ER HEUT-) 		PCLL OR	ALTER CASIN	10	₩	ATER SHI	T-OFF	X		REPAIR	INO WE	LL] .
. FRACTURE	TREAT		_	MULTIPLE	COMPLETE		71	EACTURE :	TREATMENT			ALTERI	NG CAS	INO	
SHOOT OR	VCIDIER	_	_	ABANDON*			81		OR ACIDIZING				on m en t	•	_
REPAIR WI	ELL	L		CHANGE P	LANS		(0	Ormer 3 —	pud and				Man an		
(Other) 17. DESCRIBE Proposed		• •					1		t: Report re						
		مر الأفائد مراجعة			e to 42 H-40 ca	6'. sing to	426' a	ind ce	mented	with	306.8	Cu.1	Ft.	4	
	Ran	new:	9 5/8'	[∵] 36# 1	н-40 са							Cu.]	Ft.	À	
	Ran Clas	new B	9 5/8' ' ceme n 10:4	36# Int con	H-40 ca ntainin 6-16-8	sing to g 2% CaC 5. 25 b	Cl and	1/2 o	f 1% F1	ocele	•	Cu.1	Ft.	À	
	Ran Clas	new B	9 5/8' ' ceme n 10:4	36# Int con	H-40 ca ntainin 6-16-8	sing to	Cl and	1/2 o	f 1% F1	ocele surfa	ce.			* _A	
	Ran Clas Plug Test	s "B' down	9 5/8' ' ceme n 10:4	36# Int con	H-40 cantainin 6-16-8	sing to g 2% CaC 5. 25 b	Cl and	1/2 o	f 1% F1	ocele surfa	ce.				्र स्
	Ran Clas Plug Test	s "B' down	9 5/8' ' ceme n 10:4	36# Int con 5 AM	H-40 cantainin 6-16-8	sing to g 2% CaC 5. 25 b	Cl and	1/2 o	f 1% F1	ocele surfa	ce.				
	Ran Clas Plug Test	s "B' down	9 5/8' ' ceme n 10:4	36# Int con 5 AM	H-40 cantainin 6-16-8	sing to g 2% CaC 5. 25 b	Cl and	1/2 o	f 1% F1	ocele surfa	ce.				
	Ran Clas Plug Test	s "B' down	9 5/8' ' ceme n 10:4	36# Int con 5 AM	H-40 cantainin 6-16-8	sing to g 2% CaC 5. 25 b	Cl and	1/2 o	f 1% F1	ocele surfa	ce.				
	Ran Clas Plug Test	s "B' down	9 5/8' ' ceme n 10:4	36# Int con 5 AM	H-40 cantainin 6-16-8	sing to g 2% CaC 5. 25 b	Cl and	1/2 o	f 1% F1	ocele surfa	. DE O JUN IL CO	2 a.	∫ [2 1985	V.	
	Ran Clas Plug Test	s "B' down	9 5/8' ' ceme n 10:4	36# Int con 5 AM	H-40 cantainin 6-16-8	sing to g 2% CaC 5. 25 b	Cl and	1/2 o	f 1% F1	ocele surfa	. DE O JUN IL CO		∫ [2 1985	V./	
	Ran Clas Plug Test	s "B' down	9 5/8' ' ceme n 10:4	36# Int con 5 AM	H-40 cantainin 6-16-8	sing to g 2% CaC 5. 25 b	Cl and	1/2 o	f 1% F1	ocele surfa	. DE O JUN IL CO	2 a.	∫ [2 1985	V./	
18, I hereby ce	Ran Clas Plug Test No d	downed si	9 5/8' ceme n 10:4 urface	36# Pent con 5 AM c casin	H-40 cantainin 6-16-8 ng with	sing to g 2% CaC 5. 25 b	Cl and	1/2 o	f 1% F1	ocele surfa	. DE O JUN IL CO	2 a,	∫ [2 1985	V.,	
18. I hereby co	Ran Clas Plug Test No d	downed si	9 5/8' ceme n 10:4 urface	36# Pent con 5 AM c casin	H-40 cantainin 6-16-8 ng with sure.	sing to g 2% CaC 5. 25 b	Cl and obls ci	1/2 o	f 1% F1	ocele surfa	. DE O JUN IL CO	2 a, DN. ST. 3	∫ [2 1985	· ·	
signed 1	Ran Clas Plug Test No d	downed si	cemen 10:4	36# Int con	H-40 cantainin 6-16-8 ng with sure.	sing to g 2% CaC 5. 25 b	Cl and obls ci	1/2 o	f 1% F1	ocele surfa	JUN JUN DIS	2 a, DN. ST. 3	1985 DIV	· ·	
	Ran Clas Plug Test No d	downed si	cemen 10:4	36# Int con	H-40 cantainin 6-16-8 ng with sure.	sing to g 2% CaC 5. 25 b	Cl and obls ci	1/2 o	f 1% F1 ted to es.	ocele surfa O	JUN IL CO	2 a, DN. ST. 3	1985 DIV	7-85	
SIGNED 1 (This space	Ran Clas Plug Test No d	downed su ecrea	cemen 10:4 urface ase in	36# Int con 5 AM c casin press	H-40 cantainin 6-16-8 ng with sure.	sing to g 2% CaC 5. 25 b	Cl and obls ci	1/2 o	f 1% F1 ted to es.	ocele surfa O	JUN JUN DIS	2 a, DN.: ST. 3	1985 DIV	7-85	
SIGNED 1	Ran Clas Plug Test No d	downed su ecrea	cemen 10:4 urface ase in	36# Int con 5 AM c casin press	H-40 cantainin 6-16-8 ng with sure.	sing to g 2% CaC 5. 25 t 1000# f	Cl and obls ci	1/2 o	f 1% F1 ted to es.	ocele surfa O	JUN IL CO DATE TED FO	2 Q DN: ST. 3	1985 D/V 6-17	7-85	
SIGNED 1 (This space	Ran Clas Plug Test No d	downed su ecrea	cemen 10:4 urface ase in	36# Int con 5 AM c casin press	H-40 cantainin 6-16-8 ng with sure.	sing to g 2% CaC 5. 25 t 1000# f	Cl and obls ci	1/2 o	f 1% F1 ted to es.	ocele surfa O O ACCEP	JUN JUN DIS DATE	2 a, DN.: ST. 3	1985 DIV 6-17 ECOR	7-85 D	