

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well ☐ Oil Well ☒ Gas Well Other

2. Name of Operator
BURLINGTON RESOURCES OIL & GAS

3a. Address 3401 EAST 30TH
FARMINGTON, NM 87402

3b. Phone No. (include area code)
505.326.9727

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980FWL 1930FNL

E-30-27-5

5. Lease Serial No.
SF-079367

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement Name and/or No.
SAN JUAN 27-5 UNI

8. Well Name and No.
SAN JUAN 27-5 UNIT 34A

9. API Well No.
3003923739

10. Field and Pool, or Exploratory Area
BLANCO MESAVERDE

11. County or Parish, and State
RIO ARRIBA NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input checked="" type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See attached

Electronic Submission #3360 verified by the BLM Well Information System for BURLINGTON RESOURCES OIL & GAS Sent to the Farmington Field Office
Committed to AFMSS for processing by Maurice Johnson on 04/09/2001

Name (Printed/Typed) PEGGY COLE

Title REPORT AUTHORIZER

Signature

Date 04/02/2001

THIS SPACE FOR FEDERAL OR STATE OFFICE USE ACCEPTED FOR RECORD

Approved By

Title

MR 1/2/2001

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Office

San Juan 27-5 Unit #34A

- 3-16-01 MIRU. ND WH. NU BOP. TOOH w/2 3/8" tbg. TIH w/CIBP, set @ 5250'. TOOH. TIH, perf Menefee w/1 SPF @ 4938-5215' w/21 holes total. TIH w/4 1/2" RBP, set @ 4674'. Load hole w/2% KCl wtr. PT RBP to 1000 psi, OK. SDON.
- 3-17-01 TOOH. TIH, ran CBL-CCL-GR @ 3200-4674', TOC @ 3254' (top of lnr). TOOH. SD for weather.
- 3-20-01 PT 4 1/2" csg to 3000 psi/15 min, OK. TOOH. TIH w/retrieving tool. Latch RBP, TOOH. TIH, reperf Menefee w/1 SPF @ 4938-5215' w/21 holes. TOOH. TIH w/4 1/2" pkr. PT CIBP to 3000 psi, OK. Pump 20 bbl 15% HCl across Menefee interval. TOOH w/pkr. SD waiting for frac crew.
- 3-24-01 Frac Menefee w/49,290 gal slk wtr, 898,000 SCF N2, 100,000# 20/40 Brady sd. TOOH. TIH w/frac plug, set @ 4530'. PT plug to 3000 psi, OK. Perf Lewis w/1 SPF @ 4032-4498' w/40 0.3" diameter holes total.
- 3-25-01 Acidize w/500 gal 10% acetic acid. TOOH. Frac Lewis w/674 bbl 20# linear gel, 1,147,191 SCF N2, 200,000# 20/40 Brady sd. CO after frac.
- 3-26-01 Blow well & CO.
- 3-27-01 TOOH. TIH w/3 7/8" mill. Mill out frac plug @ 4530'. TIH, blow well & CO. Mill out CIBP @ 5250'. TIH, blow well & CO.
- 3-28-01 TIH, blow well & CO to PBTD @ 5699'.
- 3-29-01 Blow well & CO. TOOH w/mill. TIH w/166 jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 5389'. (SN @ 5456'). ND BOP. NU WH. RD. Rig released.