



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA
1235 LAPLATA HIGHWAY
FARMINGTON, NEW MEXICO 87401



IN REPLY REFER TO:

SF-079366 et. al. (WC)
3162.3-1(F) (019)

JUN. 13 1991

Union Oil of California
Attention: Mr. Bill Hering
3300 N. Butler, Suite 200
Farmington, NM 87401

RECEIVED
JUN 14 1991
OIL CON. DIV.
DIST. 3

Gentlemen:

Enclosed are your Applications for Permit to Drill (APD) well Nos.:

1. No. 244 Rincon Unit, SW/4NE/4 sec. 21, T. 27 N., R. 6 W., SF-079366.
2. No. 245 Rincon Unit, SW/4NE/4 sec. 22, T. 27 N., R. 6 W., SF-079365-A.
3. No. 247 Rincon Unit, SE/4NE/4 sec. 26, T. 27 N., R. 6 W., SF-079367-A.
4. No. 248 Rincon Unit, NW/4SW/4 sec. 26, T. 27 N., R. 6 W., SF-079367-A.
5. No. 249 Rincon Unit, SE/4NE/4 sec. 27, T. 27 N., R. 6 W., SF-079366.
6. No. 250 Rincon Unit, SE/4NE/4 sec. 28, T. 27 N., R. 6 W., SF-079364.
7. No. 267 Rincon Unit, SE/4NE/4 sec. 31, T. 27 N., R. 6 W., SF-079364.
8. No. 268 Rincon Unit, NE/4SW/4 sec. 31, T. 27 N., R. 6 W., SF-079364.
9. No. 275 Rincon Unit, SE/4SW/4 sec. 24, T. 27 N., R. 7 W., SF-079298-D.
10. No. 282 Rincon Unit, NE/4NE/4 sec. 22, T. 27 N., R. 7 W., SF-079360.
11. No. 283 Rincon Unit, NE/4SW/4 sec. 23, T. 27 N., R. 7 W., SF-080385.
12. No. 284 Rincon Unit, NE/4NE/4 sec. 26, T. 27 N., R. 7 W., SF-080385.
13. No. 285 Rincon Unit, NW/4NE/4 sec. 27, T. 27 N., R. 7 W., SF-080385.
14. No. 288 Rincon Unit, SW/4SW/4 sec. 28, T. 27 N., R. 7 W., SF-080213.
15. No. 289 Rincon Unit, SE/4NE/4 sec. 33, T. 27 N., R. 7 W., SF-080213.
16. No. 296 Rincon Unit, SW/4SW/4 sec. 11, T. 26 N., R. 7 W., SF-079160.
17. No. 9 Day "B", NE/4SW/4 sec. 7, T. 27 N., R. 8 W., SF-078571.

All wells located in Rio Arriba County, New Mexico. The subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

ABANDONED LOCATION

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

Enclosures

cc:
New Mexico Oil Conservation Division
