Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED BLM

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 11 1001

_	Expires:	March	31,	1993	
	Designa		C	:-1 M:-	-

SUNDRY NOTICES AND REPORTS ON WELLS 14 7.1111: 44 SF-079366 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. 6. If Indian, Allottee or Tribe Name Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE I. Type of Well RINCON UNIT Oil Well Gas Well Other 8. Well Name and No. 2. Name of Operator RINCON UNIT 171M UNION OIL COMPANY OF CALIFORNIA 9. API Well No. 3. Address and Telephone No. 30-0392-5180 3300 N, BUTLER, SUITE 200, FARMINGTON, NM 87401 (505)326-760010. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) BASIN DK /BLANCO MV 1645' FSL & 1775' FEL 11. County or Parish, State SEC. 21, T27N, R6W RIO ARRIBA, NM 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion **New Construction** X Subsequent Report Plugging Back 5 1992 Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Other COMPLETION WORK Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* MIRU Big A pulling unit. Dril DV tool out @ 3372'. 9/1 Drilled out 2nd DV tool @ 5768'. Finished tripping 9/2 in hole to 7661' Displace hole w/2% KCL water. P.O.H. Rig up Basin Wireline, run CCL/GR/CBL from 7658'-9/3 4500', 3500'-250', had good cement bond. Perfed Dakota w/4" casing gun 4 JSPF, 120° phasing. 9/4 Rig up Western, frac Dakota down 5 1/2" casing w/ x-link gel and 245,600# 20/40 Ottawa sand. Rig down Western, rig up Basin Wireline. Set CIBP on wireline @ 5071 Ft. Tested plug to 3000 PSI-held OK. Perfed Mesa Verde w/4" casing gun 4 JSPF 120° phase. Rig down 5 1/2" csg. w/x-link gel and 244,900 20/40 Brady sand.

or representations as to any matter within its jurisdiction.	"See Instruction on Reve	artment or agency of the United States any false, fictitious or fraudulent statements FARMINGTON RESOURCE AREA
Fith 18 I I S.C. Sarrian 1001 makes in a mine for any and	i	SEP 1 4 1992
Approved by	Title	ACCEPTED FOR REGORD Date
(This space for Federal or State office use))AAPATER PAR APARAE
4. I hereby certify that the foregoing is true and correct Signed	Title FIELD CL1	ERK Date9-11-92

*See Instruction on Reverse Side NMOCD