*		
		FORM APPROVED /
ng sa khisar 🧖 💮 🕺 💮 💮 Sija sa Sija		Budget Bureau No. 1004-0135
		Expires: March 31, 1993
	norder between	5. Lease Designation and Serial No.
THE PROPERTY OF THE PROPERTY O		SF-078056
	A 1819 MANNAGARATAN LA CALABATAN	6. If Indian, Allottee or Tribe Name
Company of the state of the sta	AND THE PROPERTY OF WASTERS AND THE PROPERTY OF THE PROPERTY O	
224 S. E. SOS BEEN # 1988		7. If Unit or CA. Agreement Designation
	nangan depet despest beliefe	10 1833
**************************************	BRANCHURE SAN SERVICE AND THE SERVICE	Central Bisti Unit
		8. Well Name and No.
1. Type of Well X Oil Well	ns Well Other	,52
2. Name of Operator		9. API Well No.
Central Resources, Inc.	Im Ridge to	,30-045-05599
2 Address of Talanhone No.		10. Field and Pool, or Exploratory Area
3. Address and Telephone No.	New Mexico 87413 (505)-632-3476	Bisti Lower Gallup
P.O. Box 1213, Bloomfield, New Mexico 87413 (505)-632-3476 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State
		San Juan, New Mexico
660' FSL, 1980' FEL, Sec 31) TO INDICATE NATURE OF NOTICE, RE	PORT, OR OTHER DATA
12. CHECK APPROPRIATE BOX(S	TYPE OF ACT	TION
TYPE OF SUBMISSION	X Abandonment	Change of Plans
	Recompletion	New Construction
Notice of Intent	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Subsequent Report	I 1	Conversion to Injection
 -	Altering Casing	Dispose Water
X Final Abandonment Notice	Other	(Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Opera	tions (Clearly state all pertinent dates, including esting	nated date of starting any proposed work. If well is narkers and zones pertinent to this work.)*
directionally drilled, give subsurface loc	eations and measured and true vertical depths for all n	one Production equipment will be removed an
Central Resources, Inc. intends	s to plug the well in accordance with regulation	ons. Production equipment will be removed an
well will be plugged as specific	ed. Perforate and squeeze will be used unles	s casing can be recovered over the specified inte
there is evidence cement is in p	place behind the casing.	
Proposed Procedure:	BLM office at 505-599-8907 24 hours prior	to commencement of plugging operations.
A Notify the Fairington	whole production equipment.	
	to 1267 to 4862' to 4962'	
•	I spot cement on top to 4862' to 4962' from 3782' to 3882' across Mancos top at 38	32' inside and outside 5 1/2" casing
D. Set a 100' cement plug	from 1075' to 1162' across Pictured Cliffs a	t 1112' inside and outside 5 1/2"casing.
E. Set a 100' cement plug	from 10/5 to 1162 across returned critis a	paging shoe at 196' inside and outside 5 1/2" casi
 G. Set a cement plug from 	n surfacer to 146' to 246' across the surface of	easing shoe at 196' inside and outside 5 1/2" casi
H. Cut wellhead and insta	all dry hole marker. Clear and remediate loc	ation.
		3 3
J. da	Title Production Tech.	Date February 14, 2001
Like the	The Hodden reem	27
14. The Patty Shelton		
Si (This space for Federal or State office use)		Date 3/16/01
	Title	5/10/01
Conditions of approval, if any:		
Approved by		