

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

NMSE - 078432

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE

7. If Unit or CA, Agreement Designation

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Merit Energy Company

3. Address and Telephone No.

P.O. Drawer NN-Jal, NM 88252 (505)395-2173

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650 FSL 1650 FEL - Sec 34, T26N, R8W

8. Well Name and No.

#3 Hodges

9. API Well No.

30-045-05610

10. Field and Pool, or Exploratory Area

Ballard

11. County or Parish, State

San Juan, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9 5/8 @ 208', 5 1/2 @ 2755', producing interval 2722' to 2738'. Abandonment procedure: POOH w/tbg, set CIBP @ 2680', dump bail 20' cmt top of CIBP. Fill csg w/10# mud to 300' spot, 30' cmt plug from 300' up to 270', set surface plug top 50', cut off well head equipment, install proper 4" dry hole marker, rip & seed road & location w/proper BLM seed mixture & push up road entrance to detour traffic.

RECEIVED
MAY 23 1994
OIL CON. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct

Signed Russell White

Title West District Area Supt.

Date 5/10/94

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____

APPROVED
AS AMENDED

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

MAY 13 1994
DISTRICT MANAGER

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT
FARMINGTON DISTRICT OFFICE

1235 La Plata Highway
Farmington, New Mexico 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 3 Hoelgers

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
 2. Mike Flaniken with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
 3. The following modifications to your plugging program are to be made (when applicable):
 - 1) Set Bridge Plug @ 2626' (50' above top set of perfs - 2676'-2684')
Place 50' of cement on top of Bridge Plug.
 - 2) Set a cement plug from 2457-2357 to cover the Fruitland (2407')
plus 50% excess ~~2457-2357~~
 - 3) Set a cement plug from 2110-2010' to cover the Base of the Ojo Alamo
(Kirtland top @ 2060) plus 50% excess
 - 4) Perf @ 1953' and place cement inside & outside the 5 1/2" casing across
the Ojo Alamo top (1903) plus 100% excess
 - 5) Place cement inside & outside 5 1/2" casing from 352 to surface to
cover the Nacimiento top (302') the surface casing shoe (108') and surface.
- Office Hours: 7:45 a.m. to 4:30 p.m.