

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 078433

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

NEWMAN

9. WELL NO.

14

10. FIELD AND POOL, OR WILDCAT

GASIN DAKOTA

11. SEC., T., R., M., OR BLK. AND

SURVEY OR AREA
SEC. 29, T-26N, R-8E
N.R.P.H.

12. COUNTY OR PARISH

SAN JUAN

13. STATE

NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

SOUTHERN UNION PRODUCTION COMPANY

3. ADDRESS OF OPERATOR

P. O. Box 808, FARMINGTON, NEW MEXICO 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

1850 FT. FROM THE NORTH LINE & 1890 FT. FROM THE EAST LINE.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6450 FT. R.K.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☒

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

WE PROPOSE TO:


1. RIG UP UNIT. PULL 1-1/2 , E.U.E. TUBING.

2. DRILL OUT 4-1/2 MODEL 17 BRIDGE PLUG AT 6800 FT. R.K.B. CLEAN OUT TO P.B.T.D. OF 6951 FT. R.K.B.

3. RUN CASING INSPECTION LOG. SQUEEZE OFF ANY INDICATED HOLES WITH REQUIRED AMOUNT OF CEMENT.

4. RUN 4-1/2 PACKER AND TEST PERFORATIONS FROM 6839 FT. - 6842 FT. FOR WATER ENTRY. IF PERFS ARE MAKING WATER A 4-1/2 MODEL 17 CEMENT RETAINER WILL BE SET AT APPROX. 6800 FT. AND PERFS SQUEEZED OFF.

5. RUN 1-1/2 , E.U.E., 2.90%, JOE TUBING AND AT APPROXIMATELY 6700 FT. R.K.B.



18. I hereby certify that the foregoing is true and correct

Original signed by

SIGNED GILBERT D. NOLAND, JR.

GILBERT D. NOLAND, JR.

TITLE DRILLING SUPERINTENDENT

DATE March 11, 1974

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 14 1974

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 1: If there are no available State requirements locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.