
Land Office

Unit



Well No. 1 is located NE/4 3M/4 Sec. 21 (4 Sec. and Sec. No.) Wildcat	268 (Twp.) (R	• ,	M.H.P.H. (Meridian)	
W 1131 3	2080	······································	December 11th	, 19 <u></u> 21
(INDICATE A	BOVE BY CHECK MARK N	ATURE OF REPOR	RT, NOTICE, OR OTHER DATA)	
NOTICE OF INTENTION TO PULL OR ALTE NOTICE OF INTENTION TO ABANDON WEL	i	Supermentary well history Subsequent Report of Sand-011		
NOTICE OF INTENTION TO SHOOT OR AC	IDIZE	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF RE-DRILLING OR REPORT		
NOTICE OF INTENTION TO TEST WATER S NOTICE OF INTENTION TO RE-DRILL OR				4010.
NOTICE OF INTENTION TO DRILL	s	SUBSEQUEN	T REPORT OF WATER SHUT-OFF	E01.05 MEA

The elevation of the derrick floor above sea level is 6308 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled cement \$6 51301.

- Perforated 51111 to 51211 with 4 holes per foot. 11-24-56 Smabbed 10 bbls. clean oil, no water, in 6 hours.
- 11-25-56 Sand-oil treated with 22, 149 gallons oil and 22,500# sand, flushed with 5,121 gallons oil. Breakdown pressure 3000%, treating pressure 2000-1800#, final pressure 1000#, injection rate 30.7 barrels per minute.

After recovery of load oil, swabbing oil at rate of 2 barrels per hour. No water.

Company .	BENSON-NONTIN-GREEK DRILLI	ING CORP.
	4052 West Broadway	
	Farmington, New Mexico	By ANDESSE
		Title Vice-President



and the second of the second o

en general de la companya de la com La companya de la co