

Revised card

F. Loc. 1650/N; 990/E Elev. 6335 GL Spd. 1-19-56 Comp. 2/16/56 TD 2025 PB
Casing S. 978 @ 133 W 100 Sx. Int. @ W Sx. Pr. 7" @ 1945 W 150 Sx. T. 1 @ 1992
Csg. Perf. Prod. Stm. WF 124p. 1945-2025/34626.55000# T
AOF BO/D 817-60
I.P. 1362 MCF/D After. 3 Hrs. SICP 622 PSI After 16 Days GOR Grav. 1st Del. 4/10/66 EP

TOPS		NITD	Well Log	TEST DATA						
Kirtland	1264	C-102	Plot	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland	1705	C-103	Electric Log	2/14/56	634	1173	281	317	1125	#990
Pictured Cliffs	1963	C-104	C-110	3/5/56	435	1110	246	200	1100	#1381
Cliff House			C-122-B	4/16/57	402	650	242	200	700	
Menefee		Ditr 5-9/8-1960	Dfa 10	7/16/58	412	965	224	206	1018	
Point Lookout		Datr 11-16-60	Dac	2/2/59	391	763	221	176	726	
Mancos		11-16-60 Remarks 8/15/60 160		2/19/60	393	751	250	197	912	
Tocito				3/14/60	393	1005	231	197	1127	F5680
Dakota				4/1/60	390	212	192	1328	#5855	
Morrison				5/1/60	392	1400	212	1418		
Entrada				4/14/62	381	1137	227	191	1290	
				5/2/62	376	1177	221	1313	1122	
				7/9/64	380	1061	255	304	154	
				3/1/65	377	1001	222	275	1120	

Ballard PC Co. SJ S 22 T 26N R 9W UH Oper. EPNG Jan. | Feb. | Mar. | Apr. | May | June | July | Aug. | Sept. | Oct. | Nov. | Dec. |
Huerfano Unit No. 50