Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
14-20-603-5034

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals		6. If Indian, Allonee or Tribe Name
		Navajo
		7. If Unit or CA, Agreement Designation
SUBMIT	IN TRIPLICATE	
1. Type of Well Oil St. Gas		8. Well Name and No.
Oil X Gas Well Other 2. Name of Operator		Navajo Tribal "U" 4
Robert L. Bayless		9. API Well No.
3 Address and Telephone No.		30-045-05784 10. Field and Pool, or Exploratory Area
P.O. Box 168, Farmington, NM 87499 505/326-2659		Tocito Dome Penn. "D"
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State
Section 21, T26N, R18W		•
660' FNL & 1980' FEL B		San Juan County, NM
12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
	Abandonment	Change of Plans
X Notice of Intent	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection Dispose Water
	X Other Long term shut in	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)
	all pertinent details, and give pertinent dates, including estimated date of starti- ical depths for all markers and zones pertinent to this work.)*	ne any proposed work. If well is directionally drille
Request approval for long term other wells on the lease to ma	shut in. Bayless plans to rotate proximize ultimate oil recovery. Please 991. All wellhead valves will be seal and/or tubing will be left as is.	duction of this and refer to our letter
WIII be cicaned up. The 2000		
•• <u>•</u> * •	JUN 01 1992	OIL CON, DIV.)
		APPORTO
14. I hereby certify that the foregod is the and correct	₩ Tule Petroleum Engineer	Date _5/22/91
Signed	Title 200000	2.5
(This space for Federal or State office use)	Title	JUN 1901
Approved by		

ROBERT L. BAYLESS

P. O. BOX 168 FARMINGTON, NM 87499

FAX NO (505) 326-6911 OFFICE NO. (505) 326-2659

May 22, 1991

Bureau of Land Management 1235 La Plata Highway Farmington, NM 87401

ATTN: MR. RON FELLOWS

RE: Navajo Tribal N, P, & U Leases Lease Nos. 14-20-603-5035 14-20-603-5033 14-20-603-5034

Please refer to your recent letters concerning the status of several wells on the subject Navajo Tribal Leases. In that letter you have required Bayless to advise you of our future plans for these wells. Attached herewith are Sundry Notices for the subject wells, requesting that they be approved for long term shut in. Given Bayless' depletion plan, we urge you to consider these requests on a group basis rather than an individual well basis.

As you are aware, the subject Navajo Tribal leases are in the Tocito Dome Field which has been productive since 1963. The field is now nearly depleted. Bayless is attempting to operate these leases economically such that recovery of remaining reserves is maximized. The advanced state of depletion of the field prohibits major new investment required to bring all nonproducing wells into production. This investment would include, but not be limited to, pumping equipment and tubulars, facility and flowline repair, and compression.

Bayless plans to continue production of the subject leases by rotating production of these wells on a long term basis. Bayless believes this plan is the most effective means to maximize field ultimate recovery. The reasons supporting the plan are set forth below.

The initial fluid distribution in the Tocito Dome Field has never been fully understood, even though the reservoir was extensively cored and studied by several Amoco Engineers and Geologists. Though not apparent on open hole logs, the reservoirs in the Penn "D" are poorly connected vertically, and stratigraphically pinch out laterally. Horizontal permeability varies from poor in some zones to outstanding in others. In some areas of the reservoir water occurs above oil. The reservoir oil originally was fully gas saturated with a gas cap. As oil production continued, solution gas was liberated in the reservoir. This free gas moved up dip until a barrier encountered, and displaced oil in the process. Production also coned water in some areas, further displacing oil.