Form 3160-5 November 1983) Formerly 9-331)	UNITED STATES DEPARTMENT OF THE INTE	SUBMIT IN TRIPLICATES RIOR (Other Instructions on re-	Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. 14-20-603-5035		
1 0/11/2/19 42-331)	BUREAU OF LAND MANAGEM				
	DRY NOTICES AND REPORTS OFF OF PROPORTION FOR PERMIT— for su Use "APPLICATION FOR PERMIT— for su	ON WELLS RECEI	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
-	da Allecation for Leader		Navajo 7. Unit agreement name		
WELL X WELL	OTHER	91 MAY -2 F	月12: 56		
2. NAME OF OPERATOR		019 FARMING	8. FARM OR LEASE NAME		
Robert L.	Bayless	OTO I ANTINIC	O'Navajo Tribal "N"		
P.O. Box	168, Farmington, NM 87499 port location clearly and in accordance with) any State requirements.*	6 10. FIELD AND POOL, OR WILDCAT		
At surface	Tocito Dome Penn. "D" 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA				
14. PERMIT 80.	: 15. ELEVATIONS (Show whether	er DF, RT, GR, etc.)	Section 17, T26N, R18		
	5848 GL	5860' RKB	San Juan NM		
16.	Check Appropriate Box To Indica:	e Nature of Notice, Report, or C	Other Data		
NO	TICE OF INTENTION TO:		CENT REPORT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL		
FRACT: BE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING		
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT* X		
REPAIR WOLL	CHANGE PLANS	(Other)	of multiple completion on Well		
Other	OMPLETED OPERATIONS (Clearly state all pert	Completion or Recomp	etion Report and Log form.)		
cleaned up.					
		Mary Company			
			20 Mar 19 19 19 19 19 19 19 19 19 19 19 19 19		
			OIL CON. DIV.J .DIST. 3		
	Liability or	an to plunging of the well have. War band is revolved uppil Acradian is conspissed.	***		
	, / /		Approved		
SIGNED	$U(R) \subseteq R_{\lambda} \cap R_{\lambda}$	Petroleum Engineer	DATE 5-1-91		
Tom McC (This space for Federa	····				
APPROVED BY	TITLE _		MAY 0 9 1991		
CONDITIONS OF ▲PP	ROVAL, IF ANY:		FARMINGTON RESCRICT AND A		
	ئدمانا ماما\$	and the Payrama Cida	g.		

*See Instructions on Reverse Side

NAVAJO TRIBAL N NO. 6 PLUGGING AND ABANDONMENT

- 4/24/91 Rig up Bayless Rig 6. Pick up 48 jts. 2 3/8" tubing. Trip in on top of existing tubing and tag bridge plug at 6026. Trip out. Trip in with bridge plug.
- 4/25/91 Trip in with bridge plug and set at 4419'. Displace hole with water. Tested casing to 1000 PSI. Set cement plugs consisting of Class B as follows:

4079	-	4419	25	sacks	(30	cf)
3727			25	sacks	(30	cf)
		2877	25	sacks	(30	cf)
2070			25	sacks	(30	cf)
		1527	25	sacks	(30	cf)
surface	-	156′	25	sacks	(30	cf)

Spotted total of 42 bbls. 9 PPG mud between plugs. (236 cf).

4/26/91 Rig down. Cut off casing and erect P and A marker. Fill in pit and cut off anchors. Cleaned up location.