| Form | 9-331 |
|------|-------|
| (May | 1963) |

14. PERMIT NO.

16.

## UNITED STATES DEPARTMENT OF THE INTERIOR (Other interior verse side)

SUBMIT IN TRIP///CATE\*

|     | Form a | pprov | eđ. |         |       |
|-----|--------|-------|-----|---------|-------|
|     | Budget | Burea | u N | o. 42-R | 1434. |
| ASE | DESIGN | ATION | AND | SERIAL  | NO.   |

SF-078897

18, 26N, 11W

12. COUNTY OR PARISH | 13. STATE

New Mexico

GEOLOGICAL SURVEY

| - |          |   |   | <br> |   | <br>         |     | <br>            | <br>  |
|---|----------|---|---|------|---|--------------|-----|-----------------|-------|
| _ | <b>.</b> | _ | ^ |      | - | <br><u> </u> | ~~~ | <br>1 2 2 7 700 | <br>_ |

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

| SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.) | at a state, and a state and a state and a state a stat |
|---|--|
| L X GAS OTHER   | 7. UNIT AGREEMENT NAME   |
| ME OF OPERATOR  | 8. FARM OR LEASE NAME  |
| 1 Paso Products Company   | Western  |
| . O. Box 1560, Farmington, New Mexico   | 9. WELL NO. 4  |
| CATION OF WELL (Report location clearly and in accordance with any State requirements.* e also space 17 below.) : surface   | Gallegos Gallup 11. SEC., T., E., M., OZ ELK. AND SURVEY OR AREA   |

San Juan Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

6083' GL

| NOTICE OF INTENTION TO:                                  | SUBSEQUENT REPORT OF: |   |   |  |
|--|-----------------------|---|---|--|
| FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL  OANGE PLANS | x                     | WATER SHUT-OFF  FRACTURE TREATMENT SHOOTING OR ACIDIZING  (Other)  (NOTE: Report results of mul | REPAIRING WELL  ALTERING CASING  ABANDONMENT* |  |
| (Other)  |                       | Completion or Recompletion R  | eport and Log form.)                          |  |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

(Est. date to start work) 4-1-68

- Load hole with mud laden fluid.
- Squeeze Gallup perforations.

660'N, 1980'E, 26N, 11W

- Shoot pipe loose at free point and pull.
- Spot 100' cement plug 50' in and 50' out of stub.
- Spot 100' cement plug across top of picture cliff.
- Spot 100' cement plug at base of Ojo Alamo.
- 7. Place cement plug in top of surface with welded marker in place.
- Clean location.

MAR 2 9 1968

IL S GEOLOGICAL SURV

|   |       | - minjung - in h |  |              |   |
|---|-------|------------------|--|--------------|---|
| 18. I hereby certif; that the foregoing is true and correct |       |                  |  |              |   |
| SIGNED Jan Jam  | TITLE | Agent            |  | DATE 3-20-68 |   |
| (This space for Federal or State office use)                |       |                  |  |              | = |
| APPROVED BY   | TITLE | 3 2 2 3          |  | DA/TE        |   |
| CONDITIONS OF APPROVAL, IF ANY:                             |       |                  |  |              | _ |