

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instructions
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

66 OCT 3 PM 2:23

FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ P & A		5. LEASE DESIGNATION AND SERIAL NO. SF 078897	
2. NAME OF OPERATOR DUGAN PRODUCTION CORP.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 5820, Farmington, NM 87499 -5820		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 1980' FEL		8. FARM OR LEASE NAME Western Federal	
14. PERMIT NO.		9. WELL NO. 2	
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		10. FIELD AND POOL, OR WILDCAT Gallegos Gallup	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 7, T26N, R11W, NMPM	
		12. COUNTY OR PARISH San Juan	
		13. STATE NM	

RECEIVED

JAN 21 1992

OIL CON. DIV.
DIST. 3

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐ FULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDONMENT* ☒
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Plugged & abandoned well as follows:

- 1.) Spotted 25 sx (29.5 cu.ft.) cement plug PBTD 4190'-3975'. Squeezed to 4075'.
- 2.) Spotted 26 sx (30.68 cu.ft.) cement plug 3450'-3220' and squeezed to 3335'.
- 3.) Perfed hole @ 2330' and spotted 26 sx (30.68 cu.ft.) cement plug 2330' - 2105' and squeezed 100' cement into hole @ 2330'.
- 4.) Perfed hole @ 1450' and spotted 80 sx (94.4 cu.ft.) cement plug 1450' - 750'. Squeezed 350' into hole @ 1450'.
- 5.) Perfed hole @ 520' and spotted 65 sx (76.7 cu.ft.) cement plug 520' - surface.
- 6.) Pumped 10 sx (11.8 cu.ft.) cement down surface casing.
- 7.) Restored location.

Work done 6-10-88 thru 6-16-88.

Approved as to plugging of the well.
Liability under bond is retained until
surface restoration is complete.

18. I hereby certify that the foregoing is true and correct

SIGNED Sherman E. Dugan

TITLE Geologist

DATE 9-30-88

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE OPERATOR

OCT 07 1988
DATE

James E. Edwards
FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side