

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS ROOM

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ P & A

2. NAME OF OPERATOR  
DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR  
P.O. Box 5820, Farmington, NM 87499 -5820

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
1980' FSL & 1980' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether of, etc.)

OIL CON. DIV.

DIST. 3

5. LEASE DESIGNATION AND SERIAL NO.

SF 078897

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Western Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Gallegos Gallup

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 7, T26N, R11W, NMPM

12. COUNTY OR PARISH 13. STATE

San Juan

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plugged & abandoned well as follows:

- 1.) Spotted 25 sx (29.5 cu.ft.) cement plug PBTD 4190'-3975'. Squeezed to 4075'.
- 2.) Spotted 26 sx (30.68 cu.ft.) cement plug 3450'-3220' and squeezed to 3335'.
- 3.) Perfed hole @ 2330' and spotted 26 sx (30.68 cu.ft.) cement plug 2330' - 2105' and squeezed 100' cement into hole @ 2330'.
- 4.) Perfed hole @ 1450' and spotted 80 sx (94.4 cu.ft.) cement plug 1450' - 750'. Squeezed 350' into hole @ 1450'.
- 5.) Perfed hole @ 520' and spotted 65 sx (76.7 cu.ft.) cement plug 520' - surface.
- 6.) Pumped 10 sx (11.8 cu.ft.) cement down surface casing.
- 7.) Restored location.

Work done 6-10-88 thru 6-16-88.

Approved as to plugging and  
Liability under bond to restore  
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED Sherman E. Dugan  
(This space for Federal or State office use)

TITLE Geologist

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

NMOCC

\*See Instructions on Reverse Side

APPROVED

DATE 9-30-88

OCT 07 1988  
DATE

FARMINGTON RESOURCE AREA