16.

ATE *

5. LEASE DESIGNATION AND SERIAL NO.

| 1963) | | (Other instructions verse side) | |
|-------|--|---------------------------------|--|
| | | | |

| G. | • | |
|--|---|--|
| (Do not use this form for proposa | CES AND REPORTS ON WELLS ls to drill or to deepen or plug back to a different reservoir. CION FOR PERMIT—" for such proposals.) | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME 298 Navajo Tribal 14-20-603- |
| OIL X WELL OTHER | | 7. UNIT AGREEMENT NAME Gallegos Gallup Sand Uni |
| Skelly Oil Company | | 8. FARM OR LEASE NAME |
| . ADDRESS OF OPERATOR 1860 Lincoln Street - | - Denver, Colorado 80203 | 9. WELL NO. |
| | early and in accordance with any State requirements.* | 10. FIELD AND POOL, OR WILDCAT Gallegos Gallup |
| 1980' FSL & 660' FEL | of Section 12-26N-12W | 11. SEC., T., R., M., OR BLE. AND SURVEY OR ARMA Section 12-26N-12W |
| 14. PERMIT NO. | 15. ELEVATIONS (Show whether DF, RT, GR, etc.) | 12. COUNTY OR PARISH 13. STATE |
| | 6018' GR | San Juan New Mexico |

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO. | | SUBBRIGUENT HEROIT OF | | | | |
|-------------------------|--|-----------------------|----|---|--|--|
| | | | | , , | | |
| TEST WATER SHUT-OFF | | PULL OR ALTER CASING | | WATER SHUT-OFF | REPAIRING WELL | |
| FRACTURE TREAT | | MULTIPLE COMPLETE | | FRACTURE TREATMENT | ALTERING CASING | |
| SHOOT OR ACIDIZE | | ABANDON* | | SHOOTING OR ACIDIZING | ABANDONMENT* | |
| REPAIR WELL | | CHANGE PLANS | | (Other) | | |
| (Other) | | | | (Note: Report results of mu Completion or Recompletion I | ltiple completion on Well Report and Log form.) | |
| | | | 11 | 4 1 4 12 2 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 | | |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2/29/68 moved in and rigged up casing pulling unit. Squeezed casing perforations 5134-5164 with 15 sacks of cement. Top of cement plug 5014'. Worked 5-1/2" OD casing with 140,000# tension. Found free point at 2300'. Shot 5-1/2" OD casing at 2824'; unable to pull free. Shot 5-1/2" OD casing at 2224'; casing pulled free. Spotted 20 sack cement plug from 2174-2274'. Pulled 70 joints (2239') 5-1/2" OD 14# J-55 R2 RT&C condition "C" casing. Set dry hole marker with 10 sack cement plug in top of surface casing.

Completed P&A 3/2/68.



| | | | | . • | 1 | | | |
|---|---------|----------|----------------|------|-----------|-------------|-------------|--|
| 18. I hereby certify that the foregoing is true and corre | ect | | | | | | | |
| SIGNED Schaud Many | TITLE _ | District | Superintendent | DATE | March | 20, | 1968 | |
| (This space for Federal or State office use) | | | | | A Company | | | |
| APPROVED BY | TITLE _ | | | DATE | 1, 5 | | | |