

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

RECEIVED
DEC 10 1992

OIL CON. DIV.
DIST. 7

1. Type of Well
GAS

2. Name of Operator
Meridian Oil Inc.

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
2410'FNL, 890'FEL Sec.8, T-26-N, R-11-W, NMPM

5. Lease Number
SF-078899A
6. If Indian, All. or
Tribe Name
7. Unit Agreement Name
8. Well Name & Number
Western B #1
9. API Well No.
30-045-
10. Field and Pool
Basin Dakota
11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent	☒ Abandonment	☐ Change of Plans
	☐ Recompletion	☐ New Construction
☒ Subsequent Report	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut off
☐ Final Abandonment	☐ Altering Casing	☐ Conversion to Injection

13. Describe Proposed or Completed Operations

11-30-92 MOL&RU. ND WH. NU BOP. TOO H w/2 3/8" tbg. Set cmt @.

12-01-92 TIH to 6130', tag fill, wash to 6136'. Tag & sting into ret. Could not pump into Dk perf below ret. Press up 2500 psig. Verbal approval rec'd f/W.Townsend for changes. Sting out of ret. Cmt plug #1 w/17 sx 6130-5980'. TOO H to 5940'. Spot 19 bbl 9# 50 vis mud 5940-5135'. TOO H to 5130'. Cmt plug #2 w/17 sx 5130-4980'. TOO H to 4948'. Spot 42 bbl 9# 50 vis mud 4948-3193'. TOO H. Perf 2 holes @ 3193'. Set cmt ret @ 3143'. Est inj rate under ret & out perfs. Cmt plug #3 w/30 sx under ret, sting out & dump 17 sx on top of ret. TOO H to 2985'. Spot 52 bbl 9# 50 vis mud 2982-801'. TOO H. SDFN.

12-02-92 Perf 4 holes @ 1640'. Set cmt ret @ 1583'. Est inj rate under ret & out perfs. Cmt plug #4 w/93 sx under ret, sting out, pump 53 sx on top of ret. Perf 2 holes @ 720'. Set cmt ret @ 683'. Est inj rate under ret & out perfs. Cmt plug #5 w/75 sx under ret, sting out, pump 43 sx on top of ret. Perf 2 holes @ 284'. Est circ down csg & out bradenhead. Cmt plug #6 w/100 sx cmt until good cmt circ out bradenhead. Cut off WH. Install dry hole marker. Release rig. Well plugged & abandoned.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Affairs Date 12/3/92

(This space for Federal or State title of interest is retained until surface restoration is completed.)

APPROVED BY _____
CONDITION OF APPROVAL, if any:

APPROVED

Date 8-1-92

[Signature]
AREA MANAGER