


COPY FOR
STATE OF NEW MEXICO
**OIL CONSERVATION
COMMISSION**
SUBMIT IN TRIPLICATE TO
DISTRICT OFFICE

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Land Office Santa Fe
Lease No. 030384
Unit #1 Hickman



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL..... X	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 15, 1951

Well No. 1 Hickman is located 990 ft. from N line and 990 ft. from E line of sec. 10
NW 1/4 Sec. 10 T-26N R-12W N.M.P.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan County New Mexico
 (Field) (County or Subdivision) (State or Territory)

ground
The elevation of the derrick floor above sea level is 6075 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

5 1/2" casing was cemented at 1364 ft. w/75 sx. Hole was drilled to 1428 with cable tools. At this time no show of gas had been encountered and the well is making 3 bailers of water per hour, apparently from the bottom of the hole.

We intend to spot 100 ft. of cement in the bottom of the hole and pull the casing. A thirty foot cement plug and a steel marker will be cemented in the top of the surface pipe. The lease will be cleaned and leveled.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DON DANVERS
 Address 525 Milam Building
San Antonio, Texas
 By [Signature]
 Title Agent