

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-03523	
2. NAME OF OPERATOR Skelly Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 1860 Lincoln Street - Denver, Colorado 80203		7. UNIT AGREEMENT NAME Gallegos Gallup Sand Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FWL & 660' FSL of Section 6-26N-11W		8. FARM OR LEASE NAME	
14. PERMIT NO.		9. WELL NO. 28	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6070' GR		10. FIELD AND POOL, OR WILDCAT Gallegos Gallup	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 6-26N-11W	
		12. COUNTY OR PARISH San Juan	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
(Other) <input type="checkbox"/>			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3/10/68 moved in and rigged up casing pulling unit. Squeezed perforations 5063-5258' with 25 sacks of cement. Top of plug at 4988'. Pulled 2-3/8" OD 4.7# J-55 "C" condition tubing. Worked 5-1/2" OD casing to 160,000#. Found free point at 2500'. Shot 5-1/2" OD casing at 2476'. Spotted 20 sack cement plug from 2426-2526'. Pulled 58 joints (2481') of 5-1/2" OD 15.5# J-55 8R R3 "C" condition casing. Spotted 20 sack cement plug from 450-550'. Spotted 10 sacks of cement in top of surface casing with dry hole marker.

Completed P&A 3/12/68.



RECEIVED

MAR 22 1968

U. S. GEOLOGICAL SURVEY
FARMING

18. I hereby certify that the foregoing is true and correct

SIGNED Edward J. Franz TITLE District Superintendent DATE March 20, 1968

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: