DISTRIBUTION SANTA FE FILE U.S.G.S. LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 5a. Indicate Type of Lease State Federal Fee. 5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL GAS X OTHER- 2. Name of Operator	7. Unit Agreement Name Huerfano Unit
El Paso Natural Gas Company	8. Farm or Lease Name
3. Address of Operator	Huerfano Unit 9. Well No.
Box 990, Farmington, New Mexico - 87401	44 (P&A)
4. Location of Well H 1650 North 990	10. Field and Pool, or Wildcat
UNIT LETTER FEET FROM THE LINE AND FEET FROM	West Kutz P. C.
THE LINE, SECTION TOWNSHIP RANGE NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
Check Appropriate Box To Indicate Nature of Notice, Report or Otl	San Juan
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1603.	ALTERING CASING PLUG AND ABANDONMENT X estimated date of starting any proposed
This well has been plugged and abandoned as follows:	
Pulled tubing, checked for holes and ran tubing back in hole.	
Spotted 50 sack cement plug down tubing.	
Pulled tubing, shot 51/2" casing off at 1037', spotted a 30 sack casing stub. Pulled casing.	cement plug on
Spotted a 15 sack cement plug at surface w/a 4' x 4" P & A marker	And the
P & A completed on 4-9-69	OR CON CON
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	

CONDITIONS OF APPROVAL, IF ANY