## OIL CONSERVATION DIVISION

Revised 10/1//8

his form 1 in this he gred for moneting packers backer tents in Scotheast New Mexico

NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

,,,			NEW MEXICO PAC			Well
Operator	El Paso Natu	ral Gas Compa	iny L	easej	Huerfanito Uni	t No. 90 (MD
Location of Well: Unit		There's	26 n	e. 9	Count	, San Juan
		T#9•	Z6 Rg Type of Prod	. Method	of Prod.	Prod. Medium
N	lame of Reser	voir or Pool	(Oil or Gas)	(Flow or	Art. Lift)	(Tbg. or Csg.)
Upper Completion	Mesa Verd		Gas	1	low	Tbg.
Lower	Dakota		Gas	F	low	Csg.
Completion		PRE_	FLOW SHUT-IN PR	ESSURE DATA		
Upper Hour, da	ite 0.10 c				ss. 396	Stabilized?
			of 3 Day	psig		(¥es=or No) No Stabilized?
Lower Hour, date Length Compl Shut-in 9-12-82 time sh			-1 - 7 Dogg	SI pre	3/13	(Yes or No) No
Pomiti Shut-1	In 9-12-6	oz j chine sir	FLOW TEST N	0.1		
Commenced at (	(hour, date)*	9-15-82	FLOW TEST N	Zone p	roducing (top)	er or Lower):
	Time   Lapsed time		Pressure er Compl. Lower Compl.		Rei	
(hour, date)	since	Obber Compr.	Lowel Compl.	1 Cans		
9-13-82	1 Day	392	304		<u> </u>	
9-14-82	2 Days	395	325			
9-15-82	3 Days	396	343			
9-16-82	1 Day	330	364		Upper Zone Flowing	
9-17-82	2 Days	. 325	379		Upper Zo	ne Flowing
Production ra	te during tes	t	<u> </u>			aon
0:1.	ROPD ha	sed on	Bbls. in	Hr	s. Gr	avGOR
Gas: 65	5N	CFPD; Tested	thru (Grifice	or Meter):_ Essure Data	Meter	
Upper Hour, d	ate	Length	of	SI pre	ess.	Stabilized?
Upper Hour, date Lengt Compl Shut-in time s			ut-in	98.18	<u> </u>	(Yes or No) Stabilized?
		Length	of ut-in	SI pre	855.	(Yes or No)
Compl Shut-	ın	1 cline Sii	FLOW TEST !	NO. 2		
Commenced at	(hour, date)	<del>-</del>		Zone r		er or Lower):
Time	Lapsed time	Pre	Ssure Lower Compl.	Prod. Zone Temp.	Remarks	
(hour, date)	since **	looper compr.	Hower compre	102		
						FOR S
					SF	P231982
				<del>                                     </del>	Oll	1982
						PCN. COM.
						NST. 3
				-		
Production ra	te during te	st		3		COD
Oil:	BOPD ba	ased on	Bbls. in	Hrs	- Grav.	GOR
Gas:		_MCFPD; Teste	ed thru (Urliic	e or meter)	•	
REMARKS:						
					nd 00-51-54-54	a the best of my
	fy that the i	information h				o the best of my
knowledge.			Operat	or El Paso	Natural GasC	ompany
Approved: Oil Conservat	SEP 22 100	219		69	1	
011 Conservat	ion Division		gà	COL	Loron	
	d by CHARLES GHO		Title_	Well Te	est Coordinato	r
Title DEPUTY CIL	& GAS INSPECTOR,	DIST. #3	 Date		21, 1982	

Notified of the Mexico Pactic Liarne. That is applied to all play completed and author seven days after actual completion of the well, and annually thereafter any recribed by the order authorizate the switting completion. Such tests shall also be commenced on all miltiple completions within seven days following recompletion and/or chemical or fracture treatment, and absence recedial work has been done on a well during which the packer or the tubing have been disturbed. Tests shall also be taken at any line that commented in supported or when requested by the Formission.

2. at least 12 hours prior to the commenced of any packer leakage test, the operator shall notify the Commission in writing of the exact time the speciator shall notify the Commission in writing of the exact time the formission are shall notify the concentra shall also be so notified.

5. The packer leakage test shall commence what has stabilized, provided however, that they need not remain shall in more than seven days.

4. For flow lest 'o. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in.

5. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Mate: if, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a piceline connection the flow period shall be three hours.

5. Following completion of flow lest No. 1, the well shall again be shut-in, in accordance with Paragraph 3 above.

6. Flow Test No. 2 shall be conducted even though no leak was indicated during Flow lest No. 2 is to be the same

in, in accordance with raragraph 2 above.

6. Flow Test No. 2 shall be conducted even though no leak was indicated during Flow Test No. 1. Procedure for Flow Test No. 2 is to be the same as for flow Test No. 1 except that the previously produced zone shall remain shut-in while the zone which was previously shut-in is produced.

 Pressures for gas-zone fests must be measured on each zone with deadweight pressure gauge at time intervals as follows: 3 to as fee. deadwright pressure quije at time intervals as follows: 31 arc. tests: jessediately prior to the beginning of each flow-period, at fifteen-missive intervals during the first hour thereof, and at hourly intervals thereafter, including one pressure measurement is whistely prior to the conclusion of each flow period. 7-day tests: immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the romediately oriented the formal of each flow period. Other pressures may be taken as decired, or may be requested on wells which have previously shown questionable test data.

data.

Zi-nour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure authorized the accuracy of which must be checked at least twice, since at the beginning and once at the end of each test, with a deadwright pressure gauge. If a well is a gas-oil or an oil-gas dual consistion, the recording gauge shall be required on the oil zone only, with deadwright pressures as required above being taken on the one zone.

8. The results of the above-described tests shall be filed to triplinate within 15 days after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico Oil Conservation for mission on Northwest New Mexico Packer Leakage Test form Mexical 11-1-9%, with all deadwright pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and GOR (oil zones only). A pressure versus time curve for each zone of each test shall be constructed on the reverse side of the Packer Leakage Test form with all deadwright pressure points taken indicated thereon. For oil zones, the pressure curve should also indicate all key pressure changes which may be reflected by the recording gauge charts. These key pressure changes should also be tabulated on the form.

1000	O Mesa L	lende $\Delta$	Dakota		indicate al gauge chart front of th	I key pressure char is. These key press se Packer Leakage Te	nges which may be resure changes should a est form.	flected by the record
0								
900								
						The second secon		
800								
700								
C=2	-							
600								
500								
409	) (							
				XA-				
30a	\k				Φ			
200								
300								
		,						
100								
ł								