## UNITED STATES

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	· · · · · · · · · · · · · · · · · · ·		
Sundry Notices and Reports on Well:	5		
	lail	5.	Lease Number SF-078135
1. Type of Well GAS		6.	
		7.	Unit Agreement Name
2. Name of Operator MERIDIAN OIL			Warn-Earlie Walt
		8.	Huerfanito Unit Well Name & Number
3. Address & Phone No. of Operator			Huerfanito U #19
PO Box 4289, Farmington, NM 87499 (505) 326-9700		9.	<b>API Well No.</b> 30-045-06068
4. Location of Well, Footage, Sec., T, R, M		10.	Field and Pool
1450'FNL, 990'FEL, Sec.3, T-26-N, R-9-W, NMPM		11	Basin Fruitland Coal County and State
		11.	San Juan Co, NM
Subsequent Report Plugging Back Casing Repair Final Abandonment Altering Casing X Other - Stimulate	$\_$ Water Sh	ut o	Fracturing  Ef  Injection
13. Describe Proposed or Completed Operations			<del></del>
It is intended to initiate a capital workover on to fracture treat the Fruitland Coal.	the subjec	ct we	ll during the next year
			and the second s
			$\mathcal{L}_{\mathcal{A}}}}}}}}}}$
Δ	PR 0 1 199	17	
This approvat, experies	71 11 O T 100		Book Control of the C
14. I hereby certify that the foregoing is true and c	orrect.	٠.	——————————————————————————————————————
Signed Man Man (PMP1) Title Regulator	y Administ	trato	r_Date 4/3/96
(This space for Federal or State Office use) APPROVED BY Title	Dat	te	
CONDITION OF APPROVAL, if any:			