

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use APPLICATION FOR PERMIT for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

SF 078476

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Oxnard WN FED.

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

S. Blanco Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 15, T-27N, R-8W

12. COUNTY OR PARISH

San Juan

13. STATE

NM

1. OIL ☐ GAS ☒ OTHER

87 JUL -9 AM 11:03

2. NAME OF OPERATOR

ARCO Oil & Gas Company, Division of Atlantic Richfield Co.

3. ADDRESS OF OPERATOR

1816 E. Mojave, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

Unit L 1650' FSL & 1190' FWL.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

5916' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged 6/24/87 thru 6/26/87 as follows:

Plug	Interval	Cement	
1	1761'-2202'	40 sx	Spot plug to cover P. C. perfs and Fruitland Zone.
2	842'-1450'	50 sx	Spot plug to cover Ojo Alamo Zone. Fill hole w/mud and pressure up to 200 psi.
3	0'-105'	25 sx	Perforate 2 holes at 155'. Could not circulate. Perforate 2 holes at 125'. Could not circulate. Perforate 2 holes at 105' and circulated cement to surface.

Welded a steel plate over the top and installed a dry hole marker. Surface clean-up was completed. Reseeding will be done to BLM specifications between August 1, 1987 and September 15, 1987.

Approved as to plugging of this well by
Richard A. Remick, Production Supervisor
Bureau of Land Management

18. I hereby certify that the foregoing is true and correct

SIGNED

Richard A. Remick

TITLE Production Supervisor

DATE 7/6/87

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

JUL 15 1987

*See Instructions on Reverse Side

