## UNITED STATES DEPARTMENT OF THE INTERIOR

N	M 0	291	14		

5. LEASE

6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
8. FARM OR LEASE NAME		
<u>Federal</u>		
9. WELL NO.		
<u>#</u> 7		
10. FIELD OR WILDCAT NAME		
Blanco Pictured Cliffs		
11. SEC., T., R., M., OR BLK. AND SURVEY OR		
AREA		
<u>Sec. 9-T27N-R8W</u>		
12. COUNTY OR PARISH 13. STATE		
San Juan NM		
14. API NO.		
and Arrangement		
15. ELEVATIONS (SHOW DF, KDB, AND WD)		
GL 6200'		
(NOTE: Report results of multiple completion or zone change on Fort 9–320)		
e all pertinent details, and give pertinent dates rectionally drilled, give subsurface locations and t to this work.)*		
ug from PBTD to 50' above the ross the Fruitland top. Mesa ' and pull it. A 100' plug ub along with a 100' plug ug will be placed from 50' be-ks). The casing will be cut placed on the surface.		

Subsurface Safety Valve: Manu. and Type \_\_\_ \_\_\_\_\_ Set @ \_\_\_\_\_ Ft. - fitle Petroleum Engineerbate August 13, 1982 .....(This space for Federal or State office use) APPROVED BY APPROVAL IF ANY \_\_ TITLE \_\_ \_\_\_\_\_ DATE .\_\_ AS AMENDED

DISTRICT ENGINEER

\*See Instructions on Reverse Side

## U. S. GEOLOGICAL SURVEY Drawer 600 Farmington, New Mexico 87499-00600

Attachment to Notice of Intention to Abandon

Re: Permanent Abandonment

Well: 7 Federal

## CONDITIONS OF APPROVAL

- Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- The Farmington office (telephone (505) 325-4572) is to be notified in sufficient time for a representative to witness all plugging operations.
- Blowout prevention equipment is required.
- In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. We have asked the Bureau of Land Management for the surface restoration requirements for this well and we should be able to furnish you these requirements within 30 days. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
- The following modifications to your plugging program are to be made (when
  - a) Spot coment plug from PBTD+02300'to cover Pictured Cliffs top.
  - b) Spot cement plug from 2186 to 2086 to cover Fruitland top.
  - e) Spot coment 50' inside and 50' on top of stub.

  - d) Spot cement plug from 1620' to 1520' to cover Ojo Alamo top.
    e) Spot cement plug from 170' to surface to cover surface casing shoe,

Office Hours: 7:30 A.M. to 4:15 P.M.