

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Federal <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name Filan
3. Address of Operator PO Box 990, Farmington, NM 87401	9. Well No. 2(OWWO)
4. Location of Well UNIT LETTER <u>K</u> <u>1450</u> FEET FROM THE <u>South</u> LINE AND <u>1800</u> FEET FROM THE <u>West</u> LINE, SECTION <u>5</u> TOWNSHIP <u>27N</u> RANGE <u>8W</u> NMPM.	10. Field and Pool, or Wildcat So. Blanco P.C.
15. Elevation (Show whether DF, RT, GR, etc.) 6043'GL	12. County San Juan

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Clean out, Case Cement, Perf & Sandwater frac</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In order to increase production it is planned to workover ~~it~~ and re-stimulate this well as follows:

Clean out with mud to total depth of 2376'.

Run a full string of 2 7/8", production casing and cement with 100 sacks cement.

Selectively perforate and sandwater fracture the Pictured Cliffs formation.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed F. H. WOOD TITLE Petroleum Engineer DATE November 15, 1971

APPROVED BY [Signature] TITLE SUPERVISOR DIST. #3 DATE NOV 17 1971

CONDITIONS OF APPROVAL, IF ANY: