

STATE OF NEW MEXICO  
OIL CONSERVATION  
COMMISSION

DISTRICT NO. 3  
Phone 99 P. O. Box 697  
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 078461  
Unit NE 1/4 Sec. 5

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 29, 1952

Well No. 1 is located 1650 ft. from N line and 800 ft. from E line of sec. 5  
NE 1/4 Sec. 5 (1/4 Sec. and Sec. No.) 27 N (Twp.) 8 W (Range) 111 PM (Meridian)  
Blanco (EXT) (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drill 12 1/2 inch hole with Cable Tools to depth of 125 foot.

Set 125 feet of 10 3/4 inch casing with 75 sacks cement.

Move off Cable Tools and move on Rotary tools to drill an 8 3/4 inch hole to 2100' and set 2100' of 7 inch with 100 sacks cement.

Complete Pictured Cliff with Cable Tools in a 6 1/4" hole and shoot open hole  
casing with 300 quarts of SNG.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

OIL COMPANY: Ralph A. Johnston

DIST. 3  
Address: P. O. Box 313

Farmington,

New Mexico

By

James W. Copeland

Title

Supt.