NO. OF COPIES RECEIVED				Form C-103 Supersedes Old
DISTRIBUTION				C-102 and C-103
SANTA FE NEW MEXICO OIL CONSERVATI		SERVATION COMMISSION	Effective 1-1-65	
FILE				
U.S.G.S.				5a. Indicate Type of Lease State K Fee
LAND OFFICE	1			State X Fee 5. State Oil & Gas Lease No.
OPERATOR	,		SF 078000	
				10,0000
(DO NOT USE THIS F Use	SUNDRY NORM FOR PROPOSA	OTICES AND REPORTS ON LS TO DRILL OR TO DEPEN OR PLUG I OR PERMIT -" (FORM C-101) FOR SU	WELLS BACK TO A DIFFERENT RESERVOIR. CH PROPOSALS.)	
OIL GAS	7. Unit Agreement Name Huerfano Unit			
2. Name of Operator	8. Farm of Lease Name			
El Paso Natur	Huerfano Unit			
3. Address of Operator P. O. Box 990	9. Well No. 143			
4. Location of Well	10. Field and Pool, or Wildcat			
UNIT LETTER J	Easin Dakota			
THE East	PM.			
	12. County San Juan			
16.	Check App		Nature of Notice, Report or SUBSEQUE	Other Data ENT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	X	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB	ALTERING CASING PLUG AND ABANCONMENT
OTHER			OTHER	ding estimated date of starting any proposed
17. Describe Proposed or (work) SEE RULE 1103	Completed Operat	tions (Clearly state all pertinent de	etatis, and give perionent dates, these	and other states of the states
1.	Pick up to	ubing from Howco ceme	ent retainer.	
2.	Circulate Displacin	68 BBls of baroid cag the tubing with 10	sing packer fluid in a Bbls of diesel and 15	nnulus. Ebls of water.

THE East	LINE, SECTION TOWNSHIP _	26 N RANGE	9 W NMPM.					
	15. Elevation (Show 5401 CL	v whether DF, RT, GR, etc.)	12. County San Juan				
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:								
PERFORM REMED!AL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	Z PLUG AND ABAN CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER	D CEMENT JQB	ALTERING CASING PLUG AND ABANDONMENT]] 			
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.								
1.	Pick up tubing from Howco	cement retainer	•					
2.	Circulate 68 BBls of baroid casing packer fluid in annulus. Displacing the tubing with 10 Bbls of diesel and 15 Bbls of water.							
3.	Connect tubing back Howco cement retainer.							
4.	Swab well.							
				3				
			200	0.17				
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.								
SIGN COLLEGE	& Mondiff	Production	Engineer	DATE 13 June, 1975	=			
APPROVED BY	ur Clinia	SUMMENTES DE	SE. #3	DATE JUN 16 1976				
CONDITIONS OF APPR								