OIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

July 24, 1962

Consolidated 0il & Gas Company 2112 Tower Building, 1700 Broadway Denver 2, Colorado

Attn: Mr. Robert Tenison

Re: Packer leakage test, Consolidated #3-26 Consolidated-Hale, A-26-26N-8W

Dear Bobt

Please check your pressures during the Dakota build-up during the Pictured-Cliffs flow. According to the pressure plot I have attached an error of 100# may have been made. Re-submit packer test after your investigation.

Yours very truly

A. R. Kendrick Engineer, District #3

ARKIKS

Encl.

O'L CONSCIEVATION COMMISSION

COOR FOR SOR AGAD ACTES, NEW MEXICO

And State of the Control of the Cont

•

A CONTRACTOR OF THE CONTRACTOR