Form 3160-5 (November 1983) (Formerly 9-331)

UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

rorm approved.	
Budget Bureau No.	1004-0135
Expires August 31,	1985
	- 700

NO.

LEASE	DES	GNA	TION	AND	SERIAL
,	ATTA:	Λ 2	E03	10	

BURE	AU OF LAND MANAGEMEN	T PERFIVED	NM-03592	12		
SUNDRY NO (Do not use this form for prop Use "APPLIC	TICES AND REPORTS (concains to drill or to deepen or plug cartion FOR PERMIT—" for such p	back to a different reservoir.	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME		
1.		- 05 001 31 FILLS	7. UNIT AGREEMENT NA	VE		
OIL GAS X OTHER		MINGTON RESOURCE				
2. NAME OF OPERATOR		FARMINGTON, NEW ME	GCC 8. FARM OR LEASE NAM	<u> </u>		
Beta Development Comp	Beta Development Company			HENDERSON FEDERAL		
3. ADDRESS OF OPERATOR			9. WELL NO.	<u> </u>		
c/o Mesa Operating Lt	d Partnership, P.O.Bo	ox 2009, Amarillo,	TX #1			
LOCATION OF WELL (Report location See also space 17 below.)	clearly and in accordance with any	State requirements.	10. FIELD AND POOL, OR	WILDCAT		
At surface			Basin Dakota			
790' FNL/790' FEL			11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA			
790 FNL/790	J. FEL		SURVEY OR AREA			
			Sec. 5-26N	-11W		
4. PERMIT NO.	15. ELEVATIONS (Show whether DE	, RT, GR, etc.)		12. COUNTY OF PARISH 13. STATE		
	6234 GI	}	San Juan	NM		
		· · · · · · · · · · · · · · · · · · ·		INPI		
6. Check A	ppropriate Box To Indicate N	lature of Notice, Report, c	or Other Data			
NOTICE OF INTE			SEQUENT REPORT OF:			
TEST WATER SHUT-OFF	PT					
PRACTURE TREAT	PULL OR ALTER CASING	WATER SHUT-OFF	BEPAIRING W	BLL		
SHOOT OR ACIDIZE	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	BING		
REPAIR WELL	ABANDON* CHANGE PLANS	SHOOTING OR ACIDIZING	ABANDONMEN	r• X		
(Other)		(Other)	ults of multiple completion o			
7. DESCRIBE PROPOSED OR COMPLETED OP proposed work. If well is directinent to this work.) *						
spotted 45 sx Class Western, mixed & sp sx plug from 2032'-pumped 400 sx down and mixed & pumped 4½" annulus. No ce and up 10 3/4" x 4½ returns to surface. Witnessed by Mark P	below packer; POH to J Western; spotted 15 5 "B" cmt plug from 53 potted 100 sx cement p 776'; set retainer @ tubing and squeezed t 260 sx Class "B" ceme ment returns to surfa " annulus. Mixed & pm ND BOP's, Cut off w Philliber w/BLM. Well	sx cement Class "B 199'-4805'; RIH w/V 191ug from 3350'-203' 1606'; tstd annulus 1910elow retainer; open 1911ent thru retainer w 1912ec. Perf'd @ 491'; 1912eq 300 sx Class "B' 1912ellhead. Installed 1912ellhead. PVA 10/6/88.	"from 6160'-5964 WL; perf's @ 3351 2'; mixed & spotte to 1500 psig; mix ned 10 3/4" x 4 1, /mud returns on 10 broke circ down	RU ed 95 ced & /2" annulu) 3/4" x ===================================		
	rod Rcds, Reg, Land,	Expl.	5 5 . 1			
S. I hereby certify that the foregoing is	McKee TITLE Re	gulatory Analyst	DATE 10/28	3/88		
(This space for Federal or State offi-	ce use)		()17			
APPROVED BY	meme in	(to	ma Co Tais	and .		
CONDITIONS OF APPROVAL, IF A	NY:	Ha	CARLY SATE COOK			
	ें हैं है हूं है		ARMS ALL SALES			
	*See Instructions	on Reverse Side		responsible de la companya de la co La companya de la co		