Torm 3160-5 November 1963) Formerly 9-331) DEPARTMENT OF THE INTER			SUBMIT IN TRIPLICAT (Other instructions on P verse side)	Expires August	Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SESIAL PO.		
,		AND MANAGEMENT		NM-05791			
SUN (Do not use this	IDRY NOTICES A	AND REPORTS C	N WELLS	6. IP INDIAN, ALLOTTE	E OF TRIBE NAME		
1.			116061116	7. UNIT AGREEMENT M.	AME		
ABIT ABIT	N 97822		JAN 1 0 1986	& PARK OR LEASE HA			
Z. FAME OF OPERATOR Tenneco O	il Company			Dawson A	#*		
1 ADDRESS OF OFFICE			BUREAU OF LAND MANAGEN	EN 9 PRI DO			
••	3249, Englewoo	od, CO 80155	FARMINGTON RESOURCE A	REA 1			
4. LOCATION OF WELL (I See also space 17 bel	Report location clearly and	in accordance with any i	State requirements."	10. PIBLE AND POOL, C			
At ourface	· · · · ·			Blanco MV/B			
				SUBTET OR ABB	<u> </u>		
790' FSL, 1450'	FWL			Sec. 4, T27	Sec. 4, T27N R8W		
14. PSEMIT PO.	1	VATIONS (Show whether DF.	87, GR, etc.)		12. COUPTY OR PARISE 18. STATE		
	674	0' GR		San Juan	NM NM		
16.		te Box To Indicate N	ature of Notice, Report, a				
	NOTICE OF INTENTION TO:		80a	ENQUART REPORT OF:	 1		
TEST WATER SECT-O		LETER CABING	WATER SEUT-OFF	REPAIRING ALSERING	 		
PRACTURE TREAT AROUT OR ACIDIZE	MULTIPLE ABANDON®	COMPLETE	PRACTURE TREATMENT RECOTING OR ACIDISING	ABARBONMI	— I		
REPAIR WELL	CHANGE P		(Other)				
	ingTe Productio		(NOTE: Report res Completion or Reco details, and give pertinent da ions and measured and true ve	ults of multiple completion suspletion Report and Log fo	orma.)		
to the attached	permission to	lure. The New M	esaverde and dakot exico Oil Conserva on to be split 48%	tion Division ha	S		
				JAN 15 1986 DIL CON. DIV	النا		
813MED	the foreraing is tric and function of State office use)		ior Regulatory Ana	APPR	7/86 OVED 31986		
	م سان	*See Instructions	on Reverse Side	/ W - 1111	ENBACH ANAGER		

Form approved.

Title 18 U.S.C. Section 1001, makes it a crime for any person willfully to make to any department or agency of the United States any faise, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

511'				•
•				
3/43' A 6 7250'	o Ka		5130 17' MV 21 hoi -5365	ķs,
7452°		X	7294 13' DK 26 h 743	,/es

0351/3	
LEASE Dawson	_
WELL NO. A#1	_
CASING:	
10 3/4 "OD, 32.75LB, H-40CSG.W/ 400 S	X
TOC @ Surf . HOLE SIZE 15" DATE	_
REMARKS	_
7 5/8 "OD, 24 LB,H-40 CSG.W/ 375 S	X
TOC @ HOLE SIZE 9 7/8" DATE	
REMARKS	_
10.5	
4 1/2 "OD,& 11.6LB,J-55 CSG.W/ 144/225 S	X
TOC @ 4800'. HOLE SIZE6 1/4DATE	
REMARKS stage tool @ 5508	_
TUBING:	
	
2 3/8 "OD, 4.7 LB, <u>J-55</u> GRADE, RD, CPI	ا_
LANDED @ 7248 . , PACKER, 7250'	

DETAILED PROCEDURE:

- 1. MIRU a mast truck and WL Unit.
- Lubricate in hole with 1-3/8" hollow carrier thru-tubing perforating gun with a gun GR/CCL and correlate shooting depths to attached log sections.

Shoot 5 holes as follows:

5254' - 1 JS

5252' - 1 JS

5250' - 1 JS

5248' - 1 JS

5246' - 1 JS

Total 5' - 5 holes

- POOH w/ gun and shut well in pending notification of pipeline CO's and EPS.
- 4. File new C-104
- 5. Return well to production via 2-3/8" tbg string.