

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-5019

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo Indian

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo Tocito

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Tocito Dome

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec 9-T26N-R18W

12. COUNTY OR PARISH

Saun Juan

13. STATE

NM

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Reading & Bates Petroleum Co.

3. ADDRESS OF OPERATOR

3200 Mid-Continent Tower, Tulsa, OK 74103

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface

1980'FNL 1980'FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5696' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work).\*

Notice given to BLM office, Farmington by Don Walters w/Big "A" Well Service on 2/29/88.

Circ hole w/9.2# MUD.

Set CIBP @ 6272

Dump 4 sx cmt on CIBP.

Shoot squeeze holes @ 5495.

Squeeze cement 5395'-5495'.

Shoot squeeze holes 3772'.

Squeeze cement 3672'-3772'.

Shoot squeeze holes 2833'.

Squeeze cement 2733'-2833'.

Shoot squeeze holes 1655'.

Squeeze cement 1555'-1655'.

Shoot squeeze holes @ 1170'.

Squeeze cement 1070'-1170'.

Shoot squeeze holes 815'.

Squeeze cement 715'-815'.

Shoot squeeze holes @ 156'

Approved as to plugging of the well.  
Liability under Federal reclamation law  
surface restoration is complete.

Cement 156'-surface.

Bradenhead squeeze annulus 13-3/8"-8-5/8".

Cut off WH.

Set dry hole marker. P & A 3/3/88.

18. I hereby certify that the foregoing is true and correct

SIGNED

Matthew C. Fisher

TITLE

Sr. Engr. Technician

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

NMOCC

\*See Instructions on Reverse Side

APPROVED

DATE

3-24-88

JUL 13 1988

JAMES E. EDWARDS JR.