Form 9-331 Dec. 1973

2762.2744

Form Approved. Budget Bureau No. 42-R1424

0-1

UNITED STATES

5.	LEA	SE			
	SF	078014			

6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME Huerfano Unit
8. FARM OR LEASE NAME
Huerfano Unit 9. WELL NO. 173
173 10. FIELD OR WILDCAT NAME Basin Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 13, T-26-N, R-N.M.P.M.
12. COUNTY OR PARISH 13. STATE : San Juan New Mexico 14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD) 6609' GL
(NOTE: Report results of multiple completion or zone change on Form 9–330.)
•

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1-26-80:

1 - 27 - 8

1 - 28 - 8

1 - 31 - 8

	1 · ·	
Subsu	osurface Safety Valve: Manu. and Type	E 13 1980
0:	: Ran 214 joints 2 3/8", 4.7#, J-55 tubing 6725's	et at 6735'.
0:	Set Baker Model "N" Bridge plug at 6470'. Found leak between 3948-3828'. Set Cement Retai Squeezed. Pressure tested to 3500#, OK.	ner at 3770'.
0:	: Set Baker Model "PC" Bridge plug at 6500'. (fail	ed)
0:		