

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-5019

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo Tocito

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Tocito Dome

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 3-T26N-R18W

12. COUNTY OR PARISH

San Juan

13. STATE

N.M.

1. OIL ☐ WELL GAS ☐ WELL OTHER ☐ Unknown at this time.

2. NAME OF OPERATOR
Southern Gulf Production Company

3. ADDRESS OF OPERATOR
1801 C & I Building, Houston, Texas 77062

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1960' / 2 & 660' / 4

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, RT, CR, etc.)

5695' (CR)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☒

(Other) ☐

SUBSEQUENT REPORT OF:

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4-11-68

Perforated 6432'-6435' (4 shts./ft). Floored salt water, 695 BPD rate.

4-22-68

Spotted 25 sack cement plug across perforations 6432'-6435'. Set casing in a retainer at 6270'. Overlaid up on perforations with 4000 bag. Dropped bridging ball in retainer. Perforated 6229'-6237' (4 shts./ft). Acidize with 250 gallons 7 1/2% MCA. Swabbed, no recovery.

4-24-68

Acidize perforations 6229'-6237' with 500 gallons 15% MCA. Swabbed, no recovery.

4-27-68

Reperforated interval 6229'-6237' with 4 Tornado jets per foot. Acidize with 2000 gals 15% MCA displaced with 125 barrels salt water into formation. Swabbed, no recovery.

4-30-68

Temporarily abandon well.

18. I hereby certify that the foregoing is true and correct

SIGNED W. H. Walsh

P. E. TITLE Petroleum Engineer

Consultant

Date April 30, 1968

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

*See Instructions on Reverse Side

RECEIVED

MAY 1968

U. S. GEOLOGICAL SURVEY
ADMINISTRATIVE

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229
967-431

