UNITED STATES

| ONTIED SINIES | | | | | | | |
|---------------|---|------|----|----|---------|---|--|
| DEPARTMEN | T | OF | TH | E | INTERIO | R | |
| BIIDEAII O | F | T.AN | m | MΔ | NAGEMEN | T | |

| s on Wells |
|---|
| 5. Lease Number SF-077980A 6. If Indian, All. or Tribe Name |
| 7. Unit Agreement Name |
| |
| Huerfano Unit 8. Well Name & Number |
| Huerfano Unit #232 26-9700 9. API Well No. 30-045-21119 |
| PM Basin Fruitland Coal 11. County and State San Juan Co, NM |
| pe of Action nt Change of Plans ion New Construction Back Non-Routine Fracturing pair Water Shut off Casing Conversion to Injection timulate |
| s |
| up @ 2183'. TOOH w/69 jts 2 3/8" tbg. SDON. 6'. Load backside w/1% Kcl wtr. Pressure up sting Fruitland Coal perf @ 2022-2172' w/433 107,000# 20/40 Arizona sd. SI for gel break. . Chase pkr down hole to 1976'. Pkr came ell & CO. after frac log @ 1800-2204'. TOOH. TIH, blow 2 3/8" 4.7# J-55 8RD EUE tbg, landed @ 2098'ed. |
| Date ACCEPTED FOR RECORD OCT 25 1996 |
| |

FARMINGTON DISTRICT OFFICE