UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells			
	5.	Lease Number	
. Type of Well	6.	SF-077935 If Indian, All. or	
GAS	•	Tribe Name	
	7.	Unit Agreement Name	
Name of Operator		•	
BURLINGTON			
RESOURCES OIL & GAS COMPANY	٥	Huerfano Unit	
Address & Thomas No. of Operators	8.	Well Name & Number Huerfano Unit #242	
Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No. 30-045-21222	
Location of Well, Footage, Sec., T, R, M	10.	Field and Pool	
1025'FSL, 1550'FEL, Sec.12, T-26-N, R-10-W, NMPM	1.1	Basin Fruitland Coal	
€ NSL-3703	11.	County and State San Juan Co, NM	
NSU-3703			
CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, RE	PORT, OTHER	DATA	
Type of Submission Type of Action			
	hange of Pla ew Construct		
Subsequent Report X Plugging Back No	on-Routine	Fracturing	
Casing Repair Wa	ater Shut o		
Final Abandonment Altering Casing Co	onversion to	o Injection	
3. Describe Proposed or Completed Operations It is intended to plug back the subject well from the	e Gallup fo	rmation to the	
Fruitland Coal formation according to the att diagram.	ached proce	dure and wellbore ,	
		,	
BECFIVE	3	REC	
		S 플램 !	
DEC 1 0 1995 (i)	72 PM	
		<u>မှ</u>	
OH GON. DIV	7		
DISIL 3			
	-		
1 September 11 - September 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1			
igned May Mulhued (SCWFTC) Title Regulatory		tor Date 10/28/96	
This space for Federal or State Office use)		AFPROVE	
PPROVED BYTitle	_ Date _		
ONDITION OF APPROVAL, if any:		DEC 05 1996	
		/S/ Duane W. Spencer	
		75/ Damie W. Spences	
(5/		DISTRICT MANAGER	

NMOCO

District 6 PO Bes 1986, Hobbs, NM 88241-1986 PO Drawer OD, Artesia, NM 88211-0719 1008 Nie Brusse Rd., Aztec, NM 87416

State of New Mexico

OIL CONSERVATION DIVISION PO Box 2088 Santa Fe, NM 87504-2088

Hold criest Form C-10 Revised February 21, 199

instructions on bac

Submit to Appropriate District Offic

State Lease - 4 Copie Fee Lease - J Copn

AMENDED REPOR PO Bez 2008, Santa Fe. NM 27504-2008 WELL LOCATION AND ACREAGE DEDICATION PLAT API Number Basin Fruitland Coal 30-045-21222 71629 * Property Name · Well Number **Property Code** 242 Huerfano Unit 7139 Operator Name OGRID No. BURLINGTON RESOURCES g 65701 14538 10 Surface Location $^{\circ}$ North/South line Feet from the Feet from the East/West line UL er lot se. Section Range Lat Ida 1550 East -0 South 26 N 10 W 1025 12 0 11 Bottom Hole Location If Different From Surface Feet (rem the East West time North/South time Feet from the UL or set se. 14 Destinated Acres 15 Joint or Jaffit | 14 Conscidention Code | 15 Order No. NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION OPERATOR CERTIFICATION I haven carefy that the information contains Not resurveyed, prepared From a plat by David O. Vilven dated 1-17-73. Peggy Bradfield Printed Name Regulatory Administrator "SURVEYOR CERTIFICATION nien, and that the same is true a correct to the best of my belief. . - 1550

MERIDIAN OIL - FRUITLAND COAL RECOMPLETION PROCEDURE LAT-LONG: 36.498398 - 107.843231

Huerfano Unit #242

GENERAL WELL DATA:

Well Name: Huerfano Unit #242

Location: Unit O, Section 12, T26N, R10W, 1025' FSL, 1550' FEL

County, State: San Juan County, New Mexico

Field: Angel Peak Gallup

Formation: Gallup Elevation: 6570' GL

AFE #:

GEOLOGY:

TD: 6128'

COTD: 6110'

Surface:

Oio Alamo

1302'

Mesaverde

Gallup

3793'

Kirtland: Fruitland: 1412' 2000' Point Lookout 4616'

5682'

Pictured Cliffs

2245'

PROJECT OBJECTIVE: Plug and abandoned Gallup zone. Recomplete to Fruitland Coal utilizing extreme over balanced perforating as stimulation.

Deliver to location: 1.) 70' of 2-7/8" 6.5# J-55 lubricator tested to 5000 psi, 2.) 5000 psi frac valve, 3.) 2-7/8" flow-tee pressure tested to 5000 psi, 4.) 4-1/2" wellhead isolation tool.

- 1. Hold safety meeting. MIRU Completion Rig. Place fire and safety equipment in strategic locations. Comply with all MOI, BLM and NMOCD rules and regulations. Record all tubing, casing, and line pressures. RU flowlines. Blowdown tbg and csg, kill well w/wtr. ND wellhead. Replace any failed valves and seals on wellhead.
- 2. NU BOP's and stripping head. PU 2 jts of tubing and tag PBTD @ 6110'. TOOH with 6057' of 2-3/8" tubing. Inspect and replace any bad joints.
- 3. Plug #1 (Gallup top, 5682' 6070'): PU 4-1/2" cement retainer on 2-3/8" tubing and TIH; set retainer at 5632'. Pressure test tubing to 2000#; replace all bad joints as necessary. Load 4-1/2" TOSKS casing with water from bottom and pressure test to 500#. Mix 42 sxs class B cement. Squeeze 66 sxs below retainer, sting out of retainer and spot 4 sxs above retainer. TOOH w/ stinger.
- 4. Plug #2 (Mesaverde top, 3743' 3843'): TOOH to 3843'. Mix 12 sxs Class B cement and spot 100' cement plug across Mesaverde from 3743' to 3843'. Reverse circulate tubing clean. TOOH.
- 5. TIH w/ 4-1/2" CIBP on 2-3/8" tubing. Set @ 2300'. Load hole bottoms up with 37 bbls water. TOOH
- 6. MIRU wireline unit. Run in hole w/ CBL. Log from 2300' to surface. POOH. RD wireline unit. Provide engineering with log. Cement bond required up to 1990'. Estimated top Fruitland Coal perforation is 2002'. Contact engineering if cmt top is below 1990'. RD wireline unit.

- 7. Pressure test casing to 3500 psi. If pressure test fails contact engineering.
- 8. TIH w/ 2-3/8" tubing. Blow hole clean with air. Load hole w/ 3 bbls of 2% KCL for water cushion on top of RTG. TOOH w 2270' of 2-3/8" tubing.
- 9. TIH with 4-1/2" tree saver. NU 5000# frac valve with 2-7/8" pup joint flow tee pressure tested to 5000 psi to 4-1/2" tree saver. Run gamma ray / ccl correlation log. POOH. NU 70' of 2-7/8" lubricator pressure tested to 5000 psi. Under 5000# packoff head run 2-1/8" RTG with 5 SPF 6.7 gr 0.28" Owen charge at 60° phasing. Correlate setting depth with gamma ray log. Perforation depths for first stage are 2193'-2200'.
- 10. RU nitrogen unit. Pressure test surface lines to 5000 psi. Pressure casing w/ nitrogen to 3500 psi, approximately 43,000 scf. (1.70 psi/ft frac gradient). Hold pressure for 3 minutes and monitor for any leak-off. Have all personnel on location a minimum of 100 ft from wellhead. Holding 3500 psi on well, perforate 2193'-2200'.
- Monitor pressure on well for 15 minutes. If well does not bleed down, bleed pressure down to 200 psi. POOH with wireline. Shut-in frac valve. ND nitrogen unit. ND lubricator. Lay down 2-1/8" RTG.
- 12. NU flow back line. Flow well for 30 min on 1/2" choke. As well bleeds down increase choke size. Report flow rate every ten minutes. Take pitot gauge with well flowing to atmosphere. Shut-in frac valve
- 13. RU wireline unit. Under full lubricator, run 4-1/2" CIBP and set @ 2160'. POOH w/ wireline.
- 14. Load hole w/3 bbls of 2% KCL for water cushion on top of RTG.
- 15. NU 2-7/8" pup joint flow tee with lubricator. Under 5000# packoff head run 2-1/8" RTG with 5 SPF 6.7 gr 0.28" Owen charge at 60° phasing. Correlate setting depth with gamma ray log. Perforation depths for second stage are 2028'-2038', (possible 2002'-2012' verify w/engineering after running CNL).
- 16. RU nitrogen unit. Pressure test surface lines to 5000 psi. Pressure casing w/ nitrogen to 3,500 psi, approximately 40,000 scf. (1.70 psi/ft frac gradient). Hold pressure for 3 minutes and monitor for any leak-off. Have all personnel on location a minimum of 100 ft from wellhead. Holding 3,500 psi on well, perforate 2028'-2038'.
- Monitor pressure on well for 15 minutes. If well does not bleed down, bleed pressure down to 200 psi. POOH with wireline. Shut-in frac valve. ND nitrogen unit. ND lubricator. Lay down 2-1/8" RTG.
- 18. NU flow back line. Flow well for 30 min on 1/2" choke. As well bleeds down increase choke size. Report flow rate every ten minutes. Take pitot gauge with well flowing to atmosphere.
- 19. Control well w/ minimal 2% KCL. ND lubricator, and frac valve. Release tree saver and TOOH.
- 20. TIH w/ 3-7/8" bit on six drill collars and 2-3/8" tubing. Drill 4-1/2" CIBP @ 2160' w/ air and mist. Circulate hole clean with air. TOOH with bit and collars.
- 21. TIH with pump-off plug on bottom, Model 'F' profile nipple one joint of bottom, and remaining 2-3/8", 4.7# 8rd EUE tubing. Land tubing a minimum at +/- 2170'. Run lockdown screws in on donut.
- 22. Nipple down BOP. Nipple up wellhead assembly.

	Notify production oper first delivery.	rations that well is ready for produc	ction. Obtain 24 hr. dip-in pressure prior to	1
Com	npiled By:	Sean is alterton in S. C. Woolverton Production Engineer	0/4/96	
Арр	roved By:	J. W. Caldwell	Orilling Superintendent	_

23. Pump out plug. Blow hole clean for 1 hour. Take 1 hr pitot gauge up tubing. Shut in well. rig down.

Vendors:

Isolation Tool: Wireline Services: WSI Wellhead Service (327-3402) Basin Perforators (327-5244)

Engineer:

Sean Woolverton (H) 326-4525, (W) 326-9837,

(P) 326-8931

Pertinent Data Sheet - Huerfano Unit #242

Lat-Long: 36.498398 - 107.843231

Location:

1025'S, 1550'E, Section 12, T-26-N, R-10-W

San Juan County, New Mexico

Angel Peak Gallup Extension Elevation: Field:

6570' GL

6128' TD:

6583' KB

PBTD: 6110'

Spud Date: Completed: 4/28/73 7/03/73

44883A DP#:

Casing Record:

Top/Cement Depth Set <u>Cement</u> Casing Size Weight & Grade Hole Size 225 ft³ circ. to surface 231' 24.00# K-55 8-5/8" 12-1/4" 793 ft³ 3481' (1st Stage @ 10.50# KE 6128' 4-1/2" 7-7/8" 75% CALC)

1950' (2nd Stage -357 ft³

Temp Survey)

Tubing Record:

Depth Set Weight & Grade **Tubing Size** 6057' (Seating Nipple @ 6026') 4.7# J-55 2-3/8"

Formation Tops:

1302' Ojo Alamo 1412' Kirtland 2000' Fruitland Coal 2245' **Pictured Cliffs** 3793' Cliffhouse 4616' **Point Lookout** 5682' Gallup

Logging Record:

Electric Log, Density Log - 5/10/73 - 5/11/73 Temperature Survey

- 5/24/73 **GR-TEL**

Stimulation:

Gallup:

Slick Water Frac 5682' - 6070'

99.000# 20/40 Sand 43,030 GALS Water

Perf Diameter = 0.42", 20 Holes Total

Production History:

Cumulative Gas Production:

Current Gas Production: Cumulative Oil Production: Gallup: 0 MCF Gallup: 2245 BBLS Gallup: 0 BBLS

Gallup: 102916 MCF

Current Oil Production:

Gas: Transporter:


El Paso Natural Gas Pipeline

Oil:

Giant Refining Company

Huerfano Unit #242

AS OF 5/14/96 ANGEL PEAK GALLUP EXTENSION UNIT O, SECTION 12, T26N, R10W, SAN JUAN COUNTY, NM



Huerfano Unit #242

AS OF 5/14/96 ANGEL PEAK GALLUP EXTENSION UNIT O, SECTION 12, T26N, R10W, SAN JUAN COUNTY, NM

Proposed

GALLUP SPUD 4/28/73 COMPLETED 7/03/73


FRUITLAND @ 2000'

PICTURED CLIFFS @ 2245'

MESA VERDE @ 3793'

POINT LOOKOUT @ 4616'

GALLUP @ 5682'



PBTD 6110' TD 6128' 12-1/4" HOLE

8-5/8" 24# K-55 CSG SET @ 231' CMT W/225 FT³ CIRC. CMT TO SURFACE

2-3/8" 4.7# J-55 TBG @ 2170' SEATING NIPPLE @ 2140'

FRUITLAND COAL PERFORATION: 2028'-2038', 2193'-2210', EXTREME OVERBALANCE PERF @ 3500 PSI W/80,000 SCF N2

4-1/2" CIBP SET@2300'

SECOND STAGE CMT W/357 FT³ STAGE TOOL @ 2379' TOC @ 1950' TEMP SURVEY 7-7/8" HOLE

<u>PLUG 2:</u> 3743'-3843' CMT W/ 12 SXS CLASS B CMT PLUG

<u>PLUG 1:</u> 5582'-6070' CMT W/ 70 SXS CLASS B CMT

4-1/2" CMT RETAINER @ 5632'

4-1/2"10.5# KE CSG SET @ 6128' FIRST STAGE CMT W/793 FT³ TOC @ 3481' 75% CALC