Form 3160-5 (June 1990)

Approved by

Conditions of approval, if any:

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

BUREAU OF LAND	MANAGEMENT	Expires: Wardi 31, 1333			
	5. Lease Designation and Serial N	lo.			
SUNDRY NOTICES AND	REPORTS ON WELLS	I - 149 IND -7971			
Do not use this form for proposals to drill or to Use "APPLICATION FOR PE	o deepen or reentry to a different reservoir. 6. If Indian, Allottee or Tribe Nar RMIT - " for such proposals	ne			
	7. If Unit or CA, Agreement De	signation			
1. Type of Well Oil Well Well Other	8. Well Name and No.	жэ			
2. Name of Operator	Attention: GALLEGOS	#3			
AMOCO PRODUCTION COMPANY	Nancy I. Whitaker 9. API Well No.	3004521290			
3. Address and Telephone No.	303 830 5039	10. Field and Pool, or Exploratory Area			
P.O. BOX 800 DENVER, COLORADO 8020 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	BASIN DA	BASIN DAKOTA			
	ec. 33 T 26N R 11W UNIT D				
1010 FNL 1060 FWL So	ec. 33 1 26N K TIW GINT B SAN JUAN	NEW MEXICO			
CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER	DATA			
TYPE OF SUBMISSION	TYPE OF ACTION				
	∑ • • • • • • • • • • • • • • • • • • •				
Notice of Intent	Abandonment Change of Plans Recompletion New Construction				
Notice of intent	Plugging Back Non-Routine Fracturing				
Subsequent Report	Casing Repair Water Shut-Off Altering Casing Conversion to Injection				
Final Abandonment Notice	Other Dispose Water (Note: Report results of multiple completion o	n Well Completion or			
	Recompletion Report and Log form.				
13. Describe Proposed or Completed Operations (Clearly state all pertingular subsurface locations and measured and true vertical depths for all	inent details, and give pertinent dates, including estimated date of starting any proposed work . If well is di	irectionally drilled, give			
AMOCO PRODUCTION COMPANY HAS UNTIL OCTOBER 15, 1997.	REQUESTED AND BEEN APPROVED TO LEAVE THIS WELL IN SHU	T IN STATUS			
WE NEED AN ADDITIONAL 30 DAYS TO	SUBMIT PLANS TO PXA THIS WELL.				
		·			
		en e s			
		ŗ			
	##W 1995				
	n in the state of	A 5			
		C 5			
		() () () () () () () () () ()			
		(
14. I hereby certify that the foregoing is true and correct	Title Staff Assistant Date	05-23-1997			
14. I hereby certify that the foregoing is true and correct Signed Aug dull [This space for Federal or State office use)	Z Title Staff Assistant Date	05-23-1997 MAY 2 8 **			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fraudulent statements or representations as to any matter within its jurisdiction.

Approved by

Conditions of approval, if any:

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

5. Leese Designation and Serial No. SUNDRY NOTICES AND REPORTS ON WELLS I - 14- IND - 7971 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. 6. If Indian, Allottee or Tribe Name Use "APPLICATION FOR PERMIT - " for such proposals 7. If Unit or CA, Agreement Designation 1. Type of Well Well ⊠ Gas Well Other 8. Well Name and No. 2. Name of Operator **GALLEGOS** #3 AMOCO PRODUCTION COMPANY Nancy I. Whitaker 9. API Well No. 3. Address and Telephone No. 3004521290 303-830-5039 P.O. BOX 800 DENVER, COLORADO 80201 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) **BASIN DAKOTA** 11. County or Parish, State Sec. 33 T 26N R 11W 1010 FNL UNIT D 1060 FWL SAN JUAN **NEW MEXICO** CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF SUBMISSION TYPE OF ACTION Change of Plans Notice of Intent Recompletion **New Construction** Plugging Back Non-Routine Fracturing Subsequent Report Casing Repair Water Shut-Off Altering Casing Conversion to Injection Final Abandonment Notice (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form,) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work . If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* AMOCO PRODUCTION COMPANY REQUESTS PERMISSION TO PERMANENTLY PLUG AND ABANDON THE ABOVE WELL ACCORDING TO THE ATTACHED PROCEDURES FOR TECHNICAL INFORMATION CONTACT JANET RAY 505-326-9281 OIL GOM. DIV. Staff Assistant 08-14-1997 Title Date

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

AUG 2 1 199

Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fraudulent statements or representations as to any matter within its jurisdiction.

/S/ Duane W. Spencer

SJOET Well Work Procedure

Well:

Gallegos 3

Version:

#1

Date:

August 7, 1997

Budget:

DRA

Repair Type:

PXA

bjectives:

To PXA the entire well.

ertinent Information:

Location:

D33 T26N-R11W, 1010 FNL, 1060 FWL

Horizon: API#:

Basin Dakota 3004521290

County: State:

San Juan **New Mexico**

Engr:

Ray/Yamasaki W (505) 326-92

Lease: Well Flac:

I-149-IND-7971 or N00-C-14-20-3622 979242

Phone:

W (303) 830-58

Lease Flac: 698399

conomic Information:

APC WI:

50%

Estimated Cost:

\$20,000.00

ormation Tops: (Estimated formation tops)

Nacimento:

surface

Menefee:

2799

Ojo Alamo:

160

Point Lookout:

3745

Kirtland Shale:

360

Mancos Shale:

4079

Fruitland:

1002

Gallup:

4780

Pictured Cliffs: Lewis Shale:

1271 1408

Graneros: Dakota:

5770

Chacra:

2002 2755 Morrison:

Cliff House:

radenhead Test Information:

Test Date:

Tubing:

Casing:

BH:

Time

BH

CSG

INT

CSG

5 min	 	 		
10 min				
15 min				

Comments:

Notify regulatory agencies (BLM, NMOCD, FIMO) 24 hours in advance of plugging activity. <u>Contact BLM and indicate well is allotted</u> (FIMO regulations effective April 1, 1997).

Check location for anchors. Install if necessary. Test anchors.

MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.

TOH with 2 7/8" tubing. Run in hole with tubing and CIBP, set CIBP at 5800'. Test casing integrity to 500 psi. Spot cement plug from 5800' to 5720' (14 sacks). TOH to 4830', spot cement plug from 4830' to 4730' (17 sacks). TOH to 2805', spot cement plug from 2805' to 2705' (17 sacks). TOH to 1321', spot cement plug from 1321' to 1221' (17 sacks). TOH, rig up wireline, TIH, perforate at 1002'. Set retainer and circulate cement to surface (291 sacks). Spot 50' cement plug on top of retainer (9 sacks). TOH to 50', spot 50' cement plug at surface (9 sacks).

NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.

Contact FMC and ship surface equipment to yard or other location per instructions.


Turn over to Red Immell or Buddy Shaw for reclamation.

Rehabilitate location according to BLM or State requirements.

Gallegos 3

D33 T26N-R11W, 1010 FNL, 1060 FWL API 3004521290 I-149-IND-7971 or NOO-C-14-20-3622

Proposed PXA Wellbore Schematic



.