Form 3160-5 (Junc 1990)			FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM-26354
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry for a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals			6. If Indian, Allottee or Tribe Name
	7. If Unit or CA, Agreement Designation		
1. Type of Well Oil A Gas Well Other 2. Name of Operator The ADDIANDES ACCOUNTES TAKE			8. Well Name and No. Chaco Plant #20
J. K. EDWARDS ASSOCIATES, INC. 3. Address and Telephone No.C/O Walsh Engr. & PRod. Corp. 7415 E. Main Farmington, New Mexico 87402			9. API Well No. 30-045-22161. 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Soc., T., R., M., or Survey Description) Unit G, 1500'FNL & 900'FEL Section 27, T26N, R12W			WAW Fruitland Sand PC 11. County or Parish, State San Juan County, N.M.
12. CHECK A	PPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION		иотт	
	Report Jorument Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
		depths for all markers and zones pertinent to this work.)*	

Paul C. Thompson, Agent 5/23/95 (This space for Federal or State office use) Tide -NMOCO DISTRICT MANAGED Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement



J. K. EDWARDS ASSOCIATES

CHACO PLANT #20

P & A REPORT

- 4/26/95 Move on location and rig up. Wellhead in edge of hay field, made several attempts to spot rig before finally rigging up due to a very muddy and wet hayfield. Nipple down wellhead. Change tools out on rig to trip 1-1/4", 10 Rd, EUE tubing. Trip out of hole with 37 joints, 10 Rd, EUE tubing and lay down on float. Nipple down casing valves from 2-7/8" casing. Dig out around surface pipe. NOTE: Took 36 joints of 1-1/4" EUE tubing to storage yard at Chaco Plant. Left 1 joint of tubing on location to pump cement.
- 4/27/95 P & A well. Arrive AM on location. Cementers Inc. to perform cement work, BLM also on location. Nipple up 2-7/8" x 2 change over and 2" valve. Pump 48 sacks (57 cuft) Class "B" down 2-7/8" casing. Final pump pressure at 400#. Shut 2" casing valve, casing on vacuum.
- 4/28/95 Tag cement top at 20'. Cement with 1 sack (1.18 cuft) Class "B" down 1-1/4". Circulate to surface. Install P & A marker.

BLM representative approved procedure.