## UNITED STATES

UNITED STATES  DEPARTMENT OF THE INTERIOR	5. LEASE NM 22046
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME  8. FARM OR LEASE NAME Hard Deal
1. oil gas other Dry	9. WELL NO.
2. NAME OF OPERATOR DUGAN PRODUCTION CORP.	2  10. FIELD OR WILDCAT NAME  Nine Disturbed Cliffs
3. ADDRESS OF OPERATOR P O Box 208, Farmington, NM 87401	Nipp-Pictured Cliffs  11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec. 18, T26N R12W
below.) AT SURFACE: 1750' FNL - 1000' FEL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE San Juan NM
AT TOTAL DEPTH:  16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5972' GL
PULL OR ALTER CASING  MULTIPLE COMPLETE  CHANGE ZONES  ABANDON*  (other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertined	ee all pertinent details, and give pertinent dates, firectionally drilled, give subsurface locations and nt to this work.)*
Request permission to plug well as follows:	
<ol> <li>Plan to fill 2-7/8" 6.5#, J-55, 8R, EUE, not pBTD 1249' to surface using 34 sx cement.</li> <li>Install permanent dry hole monument.</li> <li>Fill all pits.</li> <li>Clean well location of all equipment, pipe Accomplish surface restoration as specified management agency or land owner.</li> <li>Cut or remove tie-downs.</li> </ol>	, junk, and trash.
Subsurface Safety Valve: Manu. and Type	Set @ Ft
Subsurface Salety valve, Ivialia, and Type	

18. I hereby firtify that the foregoing is true and correct 4-3-82 Agent Dugan TITLE \_ (This space for Federal or State office use) DATE TITLE APPROVED BY CONDITIONS OF APPROVAL, IF ANY: