

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1421.
5. LEASE DESIGNATION AND SERIAL NO.
N00-C-14-20-2941
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Champlin Petroleum Company	8. FARM OR LEASE NAME Pinabete-Navajo 32-2 (26-1)
3. ADDRESS OF OPERATOR P.O. Box 1257, Englewood, Colorado 80150	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface SW NE 2055' FNL, 1980' FEL, Sec. 2 1980'	10. FIELD AND POOL, OR WILDCAT Wildcat
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 2, T-26-N, R-15-W
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5862' GL	12. COUNTY OR PARISH San Juan
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data


NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Verbal permission received 12/28/77 from M.L. Seelinger, USGS, Farmington, New Mexico, to plug and abandon well as follows:

- | | |
|---|---------------------------|
| 1. TD (4750') to 4400' (350' plug) | Gallup Top 4463' |
| 2. 3590' to 3390' (200' plug) | Pt. Lookout Top 3465' |
| 3. 1025' to 875' (150' plug) | Picture Cliffs Top 950' |
| 4. 325' to 275' (50' plug) | Base of surface pipe 300' |
| 5. 30' to 0' (30' plug) | Top of surface pipe |
| 6. Dry hole marker showing well name location and Lease Number. | |



18. I hereby certify that the foregoing is true and correct

SIGNED J.N. McGirl J.N. McGirl TITLE District Drilling and Production Superintendent DATE 12/28/77

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____

*See Instructions on Reverse Side