ŀ	orm	9-331
1	Mag	1963)

WE'L X

NAME OF OPERATOR

## UNITED STATES DEPARTMENT OF THE INTERIOR (Other in verse side) GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE. instructions on

Form approved. Budget Bureau No. 42-B1424. 5. LEASE DESIGNATION AND SERIAL NO.

NOO-C-14-20-2941									
6.	IF	INDIAN,	ALLOTTEE	OR	TRIBE	NAME			

SUNDRY NOTICES A	/ND	REPORTS	ON	WELLS
------------------	-----	---------	----	-------

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME S FARM OR LEASE NAME

Pinabete-Navajo 32-2

Champlin Petroleum Company 3. ADDRESS OF OPERATOR

GAS WELL

P.O. Box 1257, Englewood, Colorado 80150

LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

1 10. FIELD AND POOL, OR WILDCAT

Wildcat 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

9. WELL NO.

SUBSEQUENT REPORT OF:

SW NE -2055 FNL, 1980 FEL Sec. 2

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO 5862' GL

Sec. 2, T-26-N, R-15-W

12. COUNTY OR PARISH | 13. STATE New Mexico San Juan

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON\* CHANGE PLANS

WATER SHUT-OFF FRACTURE TREATMENT

(Other) .

SHOOTING OR ACIDIZING

REPAIRING WELL

ALTERING CASING ABANDON MENT\*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Verbal permission received 12/28/77 from L.L. Seelinger, U.S.G.S., Farmington, New Mexico, to plug and abandon well as follows:

TD(4750') to 440' (350' plug)(113 sacks) 1.

Gallup Top 4463'

3590' to 3390' (200' plug)(92 sacks)

Pt. Lookout Top 3465'

3. 1025' to 850' (175' plug)(56 sacks) Picture Cliffs Top 950'


320' to 273' (47' plug) (15 sacks) 4.

Base of Surface Pipe 300'

30' to 0' (30' plug) (10 sacks)

Top of Surface Pipe

Dry hole marker showing well name, location and Lease Number. Well plugged and abandoned 12/30/77.



18. I hereby certify that the foregoing is true and correct

District Drilling and

1/4/78 DATE

J.N. McGirl SIGNED

Production Superintendent TITLE

PECEIVE!

APPROVED BY

CONDITIONS

DATE

U.S. Georges Co., Farmington, N.M.

P. T. McGRATH

\*See Instructions on Reverse Side

DISTRICT ENGINEER