

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-31059

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Texaco Inc. For Texaco Oils Inc.

3. ADDRESS OF OPERATOR

P. O. Box EE, Cortez, Co. 81321

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

1450' FNL & 1190' FEL

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6088' GR

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Dome Federal 24-26-13

9. WELL NO.

#3

10. FIELD AND POOL, OR WILDCAT

WAW Fruitland P. C.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 24, T26N, R13W

12. COUNTY OR PARISH

San Juan

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PCCL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☒
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The subject well was completed as plugged and abandoned, April 14, 1987.
The following procedure was carried out during the plugging operations.

1. Notified Herb Tsosie with BLM of intent to MIRU on April 2, 1987, 9:30 A.M.
2. MIRUSU, Nipple up BOPs. TOO H with 36 joints (1181') of 1 1/4", 23#/ft J-55 10 RD NUE tubing.
3. Hook up cementers to 2 7/8" casing.
4. Bullhead 50 sxs Class B cement down 2 7/8" casing. Squeezed 16 sxs into formation. Left 34 sxs inside 2 7/8" casing. No psi during cement job. Shut well in . RDMOSU.
5. April 14, 1987 cut off wellhead. Erect dry hole marker. Operations complete 4/14/87.

NOTE: Location will be seeded between July 1st and Sept 1st with the prescribed seed mix.

Approved as to plugging of the well.
Liability under bond is retained until
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED

Marl Kline

TITLE Area Superintendent

DATE 4/23/87

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

BLM (4) NMOGCC JNH LAA AAK MLK CO-OWNERS

*See Instructions on Reverse Side

APPROVED

MAY 04 1987

AREA MANAGER
FARMINGTON RESOURCE AREA